Labour Charges are capped at ₹299 per appliance

Single Door- Power Unit

Description	Service Charge
Power Cord	₹400
Power 3 Pin Plug Top	₹100
Repair - Inverter PCB (Single Door)	₹2000
Replace (New) - Inverter PCB (Single Door)	₹3201
Repair - PCB (Single Door)	₹1201

Single Door- Cooling Issue

Description	Service Charge
Damaged door - Repair	₹901
Door / gasket Adjust	₹400
Thermostat	₹700
Complete door gasket with magnet (for all model)	₹1000
Defrost Sensor	₹500

Single Door- Gas Charge

Description	Service Charge
Capillary	₹350
Dryer (Freezer)	₹160
Pin valve	₹80

Labour Charges are capped at ₹299 per appliance

Refrigerant Gas Charge (Single Door) > 100L	₹1420

Single Door Compressor

	٨.		
	٦	d	

Description	Service Charge
Inverter Compressor	₹6000
Capacitor	₹150
Relay	₹300
Over Load Protector (OLP)	₹200
Relay + OLP Combo	₹500
Compressor (Single Door) including Relay+OLP+capacitor	₹3500

Single Door- Accessories



Description	Service Charge
Drain Pipe	₹100
Drain tray	₹300
Copper pipe insulation	₹150
Door Lock	₹150
Door Switch	₹100
Bulb	₹60
LED Light	₹250
Bulb Holder	₹100

Labour Charges are capped at ₹299 per appliance

Freezer door (single door) > 200 ltr	₹650	
Freezer door (single door) upto 200 ltr	₹350	
Freezer door frame	₹450	

Single Door - Minor Repair

Description	Service Charge
Defrost cycle adjustment	₹0 ₹299 (Labour)
Door-gap fix	₹0 ₹299 (Labour)
Electrical contact fixing	₹0 ₹299 (Labour)
Pipe and fan blade adjustment	₹0 ₹299 (Labour)
Electrical Plug Adjustment	₹0 ₹299 (Labour)
Refrigerator levelling	₹0 ₹299 (Labour)
Refrigerator location correction	₹0 ₹299 (Labour)
Temperature setting	₹0 ₹299 (Labour)
Wire Retaping	₹0
Tray/Shelf Adjustment	₹0 ₹299 (Labour)

Labour Charges are capped at ₹299 per appliance

Double Door- Power Unit

~~	

Description	Service Charge
LVT	₹750
Power 3 Pin Plug Top	₹100
Power Cord	₹400
Repair - Inverter PCB (Double Door)	₹2200
Repair - PCB (Double Door)	₹1451
Replace (New) - PCB (Double Door)	₹0 ₹299 (Labour)

Double Door- Defrost Issue



Description	Service Charge
Coil Heater	₹1650
Defrost Sensor	₹550
Defrost Timer	₹850
Duct and Drain Cleaning	₹300
Glass Heater	₹900
P Cord heater	₹1000
Bimetal	₹500
Thermal Fuse	₹200
Thermal Fuse and Bimetal both	₹700

Labour Charges are capped at ₹299 per appliance

Double Door- Gas Charge

∿.	/
- 7	~

Description	Service Charge
Capillary	₹350
Condensor coil	₹1200
Cooling Coil (Double Door)	₹2500
Drain Tray Condensor	₹500
Dryer (Freezer)	₹160
Pin valve	₹80
Refrigerant Gas Charge (Double Door)	₹1890
Step Valve	₹1200

Double Door Compressor Unit



Description	Service Charge
Capacitor	₹150
Compressor including Relay,OLP,Capacitor <500 lit.	₹5400
Compressor (Double Door) including Relay,OLP and Capacitor >500 liter	₹5830
Inverter Compressor	₹7500
Over Load Protector (OLP)	₹300
Relay	₹350
Relay + OLP + Capacitor	₹800

Labour Charges are capped at ₹299 per appliance

AC Fan Motor	₹1200
Damaged door - Repair	₹901
Damper Thermostat	₹1050
DC Fan Motor - Freezer	₹1800
DC Fan Motor - Refrigerator	₹1900
Defrost Sensor	₹500
Hitachi door repair 440 ltr.	₹1300
Fan blade	₹120
Ref door gasket & magnet above 400Ltrs	₹2200
Ref door gasket & magnet below 400Ltrs	₹1700
Room Sensor	₹550
Rotary Switch	₹600
Thermocol duct repair	₹500
Thermostat	₹800

Double Door- Accessories



Description	Service Charge
Bulb	₹50
Bulb Holder	₹150
Copper pipe insulation	₹170
Door Lock	₹435

Labour Charges are capped at ₹299 per appliance

Drain tray	₹300
LED Light	₹290
Magnetic door switch	₹200
Thermostat knob	₹50
Door Leg	₹50

Side-by-Side Door- Power Unit

V

Description	Service Charge
LVT	₹750
Power 3 Pin Plug Top	₹120
Power Cord	₹350
Repair - Inverter PCB (SBS)	₹2600
Repair - PCB (SBS)	₹2200
Replace (New) - PCB (SBS)	₹1 ₹299 (Labour)

Side-by-Side Door- Cooling Issue



Description	Service Charge
AC Fan Motor	₹1200
Damper Thermostat	₹1050
Fan blade	₹120
Room Sensor	₹600

Labour Charges are capped at ₹299 per appliance

Thermostat	₹850
DC Fan Motor - Freezer	₹1900
DC Fan Motor - Refrigerator	₹1900
DC Fan Motor - Condenser	₹1900
Door/Gasket adjust	₹200
Damaged door - Repair	₹901

Side-by-Side Door- Gas Charge

Description	Service Charge
Capillary	₹350
Condensor coil	₹1400
Dryer (Freezer)	₹170
Pin valve	₹90
Cooling Coil (Side By Side)	₹2900
Refrigerant Gas Charge (SBS)	₹2300
Sub Condensor	₹800
Drain Tray Condenser	₹500
Step Valve	₹1200

Side-by-Side Door- Compressor Unit

Labour Charges are capped at ₹299 per appliance

Over Load Protector (OLP)	₹350
Relay	₹400
Relay + OLP + Capacitor	₹900
Compressor (Side By Side) including Relay, Olp and Capacitor	₹6600

Side-by-Side Door- Defrost Issue

~

Description	Service Charge
Thermal Fuse	₹200
Thermal Fuse and Bimetal both	₹700
Defrost Sensor	₹600
Glass Heater	₹900
P Cord heater	₹1000
Defrost Sensor with Thermal fuse	₹700
Heater Coil	₹1650
Rod Heater	₹1000
Drain and Duct cleaning	₹300
Defrost Timer	₹1000

Side-by-Side Door- ICE/Water dispenser

~

Description	Service Charge
Ice maker kit	₹2500

Labour Charges are capped at ₹299 per appliance

Ice / Water lever switch	₹250
Ice /Water solenoid valve	₹1200
Ice Storage box	₹0
Replace ice Blade or flap	₹1
Ice tray	₹550
Water / Ice dispenser lever	₹1200
Water Filter	₹2000
Water pipe/connector 3 meter	₹350
Water tank with Pipe	₹1400

Side-by-Side Door- Accessories



Description	Service Charge
Bulb	₹50
Copper pipe insulation	₹170
Door switch	₹250
Drain Pipe	₹100
Drain tray	₹400
LED Light	₹290
Magnetic door switch	₹200
Bulb Holder	₹100
Temperature Knob	₹50

Labour Charges are capped at ₹299 per appliance

Side-by-Side Door-Minor Repair

~	/

Description	Service Charge
Defrost cycle adjustment	₹0 ₹299 (Labour)
Door-gap fix	₹0 ₹299 (Labour)
Electrical contact fixing	₹0 ₹299 (Labour)
Pipe and fan blade adjustment	₹0 ₹299 (Labour)
Refrigerator levelling	₹0 ₹299 (Labour)
Electrical Plug Adjustment	₹0 ₹299 (Labour)
Refrigerator location correction	₹0 ₹299 (Labour)
Temperature setting	₹0 ₹299 (Labour)
Wire Retaping	₹0
Tray/Shelf Adjustment	₹0 ₹299 (Labour)
Drain Tray Adjustment	₹0 ₹299 (Labour)
Minor Repair - Others	₹0 ₹299 (Labour)