

Implement measures to prevent similar defects from occurring in future product batches.
Step 7: Document the Resolution
Document the details of the defect resolution, actions taken, and any compensation or remediation provided for future r