

Category	Details
Project Name	x
Project ID	х
Project Location	х
Company Name	ICoM GmbH
Inspector Name	Max Mastermann
Date of Inspection	02/04/2025
Damage & Object Type(s)	JTape (Joint Tape), Weathering, Rust
Impact	The rust staining and weathering of the concrete surface, possibly due to prolonged exposure to moisture and environmental factors.
Size	The rust staining appears to be localized, affecting a small area of the concrete surface.
Direction	Horizontal (along the length of the wall).
Possible Reasons	The rust staining and weathering could be attributed to the concrete being exposed to moisture for an extended period, leading to the development of rust and the surrounding deterioration of the concrete structure.