Landslide Early Warning

නායයෑම් පිළිබඳ පෙර අනතුරු ඇහවීම

மண்சரிவு முன்னெச்சரிக்கை

Message ID: LEWM-08-11-2021-2030-13

Update: 13 th update

Validity Period: From 20:30 hrs on 08.11.2021 To 20:30 hrs on 09.11.2021



NATIONAL BUILDING RESEARCH ORGANISATION ජාතික ගොඩනැගිලි පර්යේෂණ සංවිධානය

தேசிய கட்டிட ஆராய்ச்சி நிறுவனம் No. 99/1, Jawatta Road, Colombo 05. අංක. 99/1, ජාවත්ත පාර, කොළඹ 05. இல. 99/1, ஜாவத்தை வீதி, கொழும்பு 05.

Tel./දූ.2ක./தொ.பே - 0112552220

Fax/ෆැක්ස්/தொ.ந - 0112589943

Since the rainfall within the past 24 hours has exceeded 75mm, if the rain Warning level 1: Watch continues, be watchful on the possibility of landslides, slope failures, rock Color Code: Yellow falls, cutting failures and ground subsidence. අදියර 1 : විමසිලිමත් පසු ගිය පැය 24 තුල වර්ෂාපතනය 75mm ඉක්මවා ඇති බැවින්, වර්ෂාව වර්ණ කේතය: කහා තවදුරටත් පවතී නම් නායයෑමේ, බෑවුම් කඩා වැටීමේ, ගල් පෙරළිමේ, පස් කණ්ඩ් කඩා වැටීමේ සහ පොළොව ගිලා බැසීමේ අවදානම පිළිබදව எச்சாிக்கை மட்டம் 1: அவகானிப்ப வர்ண குறியீடு: විමසිලිමත් වන්න. மஞ்சள் குடந்த 24 மணித்தியாலங்களில் மழைவீழ்ச்சி மி.மீ மேவியுள்ளதனால்- மழை தொடருமாயின் மண்சரிவு, சாய்வு இடிந்து விழுகை, விழுகை, நிலவெட்டுசாய்வு இழந்து விழுகை மற்றும் உள்ளிறக்கம் என்பவற்றின் சாத்தியங்களுக்கான அவதானிப்புடன் இருக்கவும். Since the rainfall within the past 24 hours has exceeded 100 mm, if the Warning level 2: A1ert rains continue, be on alert on the possibility of landslides, slope failures, Amber Color Code: rock falls, cut failures and ground subsidence, being ready to evacuate to a safe location if the need arises. අවධාන අදියර 2 : වර්ණ කේතය: ඇම්බර් පසුගිය පැය 24 තුළ වර්ෂාපතනය 100 mm ඉක්මවා ඇති බැවින්, වර්ෂාව තවදුරටත් පවතී නම් නායයෑම්, බෑවුම් කඩා වැටීම්, ගල් පෙරළීම්, எச்சாிக்கை மட்டம் 2: எச்சரிக்கை පොළොව ගිලා බැසීමේ සහ පස් කණිඩ් කඩා වැටීම් අවධානම පිළිබද வர்ண குறியீடு: செம்மன்சள் අවධානයෙන් සිට අවශා වූවහොත් ආරක්ෂාකාරී තැනකට යාමට සුදානම් වන්න. 24 மணித்தியாலங்களில் மழைவீழ்ச்சி 100 மி.மீ மேவியுள்ளதனால்- மழை தொடருமாயின் மண்சரிவு, சாய்வு இடிந்து-விழுகை, பாறை-விழுகை, நில்வெட்டுசாய்வு இடிந்து-விழுகை மற்றும் தரை-உள்ளிறக்கம் என்பவற்றின் சாத்தியங்களையிட்டு எச்சரிக்கையுடன்- தேவையேற்படின் பாதுகாப்பான இடங்களுக்கு வெளியேறும் தயார் நிலையில் இருக்கவும். Since the rainfall within the past 24 hours has exceeded 150 mm, if the Warning level 3: Evacuation rains continue, evacuate to a safe location to avoid the risk of landslides, Color Code: Red slope failures, rock falls, cutting failures and ground subsidence. ඉවත්වීම අදියර 3 : පසුගිය පැය 24 තුළ වර්ෂාපතනය 150mm ඉක්මවා ඇති බැවින්, වර්ෂාව වර්ණ කේතය: රතු තවදුරටත් පවතී නම් නායයෑම්, බෑවුම් කඩා වැටීම්, ගල් පෙරළීම්, எச்சாிக்கை மட்டம் 3: வெளியேறுகை පොළොව ගිලා බැසීම් සහ පස් කණ්ඩ් කඩා වැටීමේ අනතුරු වලින් வர்ண குறியீடு: சிவப்பு වැලකීමට ආරක්ෂිත ස්ථානයකට යන්න. 24 மணித்தியாலங்களில் மழைவீழ்ச்சி 150 மி.மீ மேவியுள்ளதனால்- மழை தொடருமாயின் மண்சரிவு, சாய்வு இடிந்து விழுகை, பாறை விழுகை, நிலவெட்டுசாய்வு இடிந்து விழுகை மற்றும் உள்ளிறக்கம் என்பவற்றின் அபாயங்களை தவிர்ப்பதற்காக பாதுகாப்பான

பகுதிகளுக்கு வெளியேறவும்.

Locations for Potential Risk නායයෑමේ අවදානම පැවතිය හැකි පුදේශ கனதியான அபாயமுள்ள இடங்கள்				
District	Level 1 (Yellow)	Level 2 (Amber)	Level 3 (Red)	
Badulla	Ella and Passara Divisional Secretariat Division(s) (DSD) and surrounding areas.			
Colombo	Seethawaka and Padukka Divisional Secretariat Division(s) (DSD) and surrounding areas.			
Galle	Yakkalamulla, Neluwa, * Akmeemana, Nagoda and * Galle Four Gravets Divisional Secretariat Division(s) (DSD) and surrounding areas.	Elpitiya and Baddegama Divisional Secretariat Division(s) (DSD) and surrounding areas.		
Kalutara	Ingiriya, Walallawita, Dodangoda and Horana Divisional Secretariat Division(s) (DSD) and	Bulathsinhala, Palindanuwara, Agalawatta and * Mathugama Divisional Secretariat Division(s) (DSD) and		
Kandy	surrounding areas. Yatinuwara, Udunuwara, Doluwa, Harispattuwa, Gangawata Korale, Pasbage Korale and Udapalatha Divisional Secretariat Division(s) (DSD) and surrounding areas.	this production of the surrounding areas. ↑ Ganga Ihala Korale Divisional Secretariat Division(s) (DSD) and surrounding areas.		
Kegalle	Deraniyagala, Ruwanwella, Warakapola, Galigamuwa and	Aranayaka, Bulathkohupitiya, Mawanella, Rambukkana,		

	Yatiyanthota	Dehiowita and	
	Divisional Secretariat	Kegalle	
	Division(s) (DSD) and	Divisional Secretariat	
	surrounding areas.	Division(s) (DSD) and surrounding areas.	
	Rideegama,	surrounding areas.	
	Mawathagama and Mallawapitiya	Narammala	
Kurunegala	1 3	Divisional Secretariat	
	Divisional Secretariat	Division(s) (DSD) and	
	Division(s) (DSD) and surrounding areas.	surrounding areas.	
	Rattota and Ukuwela		
Matale	Divisional Secretariat Division(s) (DSD) and surrounding areas.		
Nuwara Eliya	Walapane, Hanguranketha, Ambagamuwa and Kotmale		
	Divisional Secretariat Division(s) (DSD) and surrounding areas.		
	Kuruwita, Nivithigala,	Ayagama, Ratnapura,	
Ratnapura	Elapatha and Kiriella	Kalawana and Eheliyagoda	
	Divisional Secretariat	Divisional Secretariat	
	Division(s) (DSD) and	Division(s) (DSD) and	
	surrounding areas.	surrounding areas.	

Note: \uparrow shifted one level up, $\uparrow \uparrow$ shifted two levels up, \downarrow shifted one level down, $\downarrow \downarrow$ shifted two levels down. *newly added with the last update

Special Note: These warning levels are issued based on the cumulative rainfall received to respective areas and given weather forecast by meteorological department of Sri Lanka

Areas and places which need special attention

All mountainous areas, manmade cut slopes and roads within the relevant DS divisions අදාල පාදේශීය ලේකම් කොට්ඨාශ තුල පිහිටි කඳුකර බෑවුම් හා ඒ ආශිත පුදේශ තුල පිහිටි නිර්මිත

பிரதேச செயலக பிரிவினுள்ளான சகல மலைப்பாங்கான பகுதிகள் மற்றும் வெட்டப்பட்ட நிலச் சாய்வுகள்

Specially: All the landslide susceptible areas previously identified by NBRO.

විශේෂ: ජාතික ගොඩනැගිලි පර්යේෂණ සංවිධානය විසින් නායයැමේ අවදානමක් ඇති ලෙස පුර්වයෙන් හදුනාගෙන ඇති පුදේශ **விசேடமாக:** டீசுழுவினால் முன்னா் அடையாளப்படுத்தப்பட்ட மண்சாிவுக்கான ஏதநிலையுள்ள சகல பிரதேசங்கள்.

විශේෂ සටහන: කරුණාකර මෙම නායයැම් පිළිබඳ පූර්ව අනතුරු හැඟවීම් කාලසීමාව තුළ පහත කරුණු වෙත ඔබේ අවධානය යොමු කරන්න.

- පහත දැක්වෙන නායයෑම් පූර්ව ලක්ෂණ පිළිබඳ සැලකිලිමත් වන්න.
 - පොළවේ ඇති වන ඉරි තැලීම්, ගැඹුරට හැරුණු පැළුම් හා පොළවේ ගිලා බැසීම්
 - කුමයෙන් ඇලවී යන ගස්, විදුලි කණු, වැටවල් හා දුරකථන කුළුණු ආදිය
 - 🗲 ගොඩනැගිලිවල ගෙබිම හා බිත්තිමත ඇතිවන පිපුරුම් හා ඒවායේ කුමික වර්ධනය වීම්
 - එක්වර ජල උල්පත් ඇතිවීම හෝ පෙර පැවති ජල උල්පත්බොරවීම, අවහිරවීම හෝ නැතිවීම
- 2. එවත් නායයාමක පූර්ව ලක්ෂණ දක්නට ලැබෙන පුදේශ වලින් හැකි ඉක්මනින් ඉවත් වන්න.
- 3. ඊට අමතරව අනතුරට භාජනය වියහැකි යැයි අනුමාන කරන පුදේශ වල ජිවත් වන පුද්ගලයින් වැඩි වශයෙන් පරීක්ෂාකාරී වියයුතු අතර දැඩි වර්ෂා තත්වය තවදුරටත් පැවතුනභොත් සුරක්ෂිත ස්ථානයක් කරා ක්ෂණිකව ඉවත්ව යාමට සුදානම්ව සිටිය යුතුය.

සැ.යු: ජාතික ගොඩනැගිලි පර්යේෂණ සංවිධානයෙන් සහ ආපදා කළමනාකරණ මධාස්ථානයෙන් ලැබෙන වැඩිදුර උපදෙස් අනුගමනය කරන්න.

Special Note: During this Landslide Early Warning period, please pay attention to the following:

- 1. Pay your attention to the following pre landslide signs,
 - Development of cracks on the ground, deepened cracks and ground subsidence
 - > Slanting of trees, electrical posts, fences and telephone posts
 - > Cracks in the floors and walls of buildings which are built at slopes
 - Sudden appearance of springs, emerging muddy water, blockage or disappearance of existing springs
- 2. People should move immediately away from the areas where they noticed the above pre-landslide signs.
- Furthermore, people living in landslide susceptible areas should be extra vigilant and should be ready to move quickly to safe places if heavy rain continues.

Note: Communities are advised to follow the instructions given by National Building Research Organization and Disaster Management Center.

விசேட குறிப்பு: மண்சரிவு முன்னெச்சரிக்கை காலப்பகுதியில் பின்வருவனவற்றில் கவனம் எடுக்கவும்

- பின்வரும் மண்சரிவு முன் அறிகுறிகளையிட்டு கவனத்தை செலுத்தவும்.
 - நிலத்தில் வெடிப்பு உருவாகுதல், ஆழமாகும் வெடிப்புகள் மற்றும் தரை உள்ளிறக்கங்கள்.
 - மரங்கள்,மின் கம்பங்கள், வேலிகள், மற்றும் தொலைபேசிக் கம்பங்கள் சாய்வடைதல்.
 - 😕 சாய்வுகளில் அமைந்துள்ள கட்டிடங்களின் தரைமற்றும் சுவர்களில் வெடிப்புகள் உருவாகுதல்.
 - நிலத்திலிருந்து திடீரென நீரூற்றுகள், சேற்று நிர் தோன்றுதல் மற்றும் தற்போதுள்ள நீரூற்றுகள் தடைப்படுதல் அல்லது இல்லாது போகுதல்.
- மண்சரிவுக்கு முன்னரான அறிகுறிகளை கொண்ட இடங்களிலிருந்து உடனடியாக மக்கள் அப்பால் நகர வேண்டும்.
- மேலும், பாதிப்பு ஏதுநிலையுள்ள பகுதிகளில் வாழும் மக்கள் மேலதிக விழிப்புடன் இருக்கவேண்டும் என்பதுடன் கடும் மழை தொருமாயின் விரைவாக பாதுகாப்பான இடங்களுக்கு நகர ஆயத்தமாகவும் இருக்கவேண்டும்.

குறிப்பு: தயவுசெய்து தேசிய கட்டிட ஆராய்ச்சி நிறுவனம் மற்றும் அனர்த்த முகாமைத்துவ நிலையம் என்பவற்றின் அறிவுறுத்தல்களை பின்பற்றவும்

Previous Message ID : LEWM-08-11-2021-1600-12	

Issued by:	Approved by:	
Rathreyoke	2/m/2 de	08-11-2021, 20:30 hrs Date and time issued
Duty Officer	Director - LRRMD	


Landslide Research and Risk Management Division

National Building Research Organisation



Automated Landslide Early Warning Map

Landslide Early Warning Center National Building Research Organisation, Sri Lanka



Warning Status

Message Type

Update

Message ID

LEWM-08-11-2021-1600-12

Valid Period

From: 16:00 hrs on 08.11.2021 To: 16:00 hrs on 09.11.2021

Previous Message ID

LEWM-07-11-2021-2030-11

Last Update

08-11-2021 03:44:50 PM

Legend

Warning Level 1	Watch
Color Code	
Warning Level 2	Alert
Color Code	