



STATUS

Open

PRIORITY

High

DUE DATE

10/16/2026

ESTIMATED TIME

1h

WORK TYPE

Reactive

REQUEST

#14251998

DESCRIPTION

Every Friday we have to sweep up a trash cans worth of regrind dust from out side by the silos. I have verified that the filters are being cleaned at least once per shift but yet this continues to happen. With winter approaching we won't be able to clean this up as often. It seems like the current system isn't the right one for what we are doing.

ASSIGNEES

Joshua Schroeder

Steve Huddleston

CATEGORIES

Work Order Request

Engineering

PART STATUS

No Part

PICTURES



LOCATION

Vacuum Pump Room

ASSET

Material Vacuum Pumps

Time & Cost Tracking

No time entries or costs recorded

WORK ORDER INFO

Created by: Steve Huddleston on 10/02/2026, 7:07 AM

Last updated on 10/05/2026, 6:51 AM

Requested by Chad Nye on 10/01/2026, 4:21 PM

COMMENTS

Email sent to Matt Trump (ACS Regional Manager) to find a solution to this issue.

Commented by Joshua Schroeder on 10/02/2026, 10:44 AM

Current filter setup

Commented by Joshua Schroeder on 10/02/2026, 12:50 PM

WORK ORDER HISTORY

Chad Nye requested the work order

10/01/2026, 4:21 PM

Steve Huddleston created work order

10/02/2026, 7:07 AM

Steve Huddleston changed the due date from 10/02/2026 to 10/16/2026

10/05/2026, 6:51 AM

Steve Huddleston changed the title from "The current vacuum pump filter system does not seem to be designed for heavy regrind use!" to "VACUUM PUMP FILTERATION UPGRADE".

10/05/2026, 6:51 AM

Signed off by

Date