CENTENNIAL AIRPORT (APA) ARRIVAL ALERT

Landing South
RWY 17R and RWY 17L



Pilots confuse RWY 17L for RWY 17R.

Not for Navigational Purposes
For Situational Awareness Only

CENTENNIAL AIRPORT (APA) ARRIVAL ALERT

Landing North
RWY 35L and RWY 35R



Pilots confuse RWY 35R for RWY 35L.

Not for Navigational Purposes
For Situational Awareness Only

Office of Primary Responsibility (OPR): ATO, Runway Safety
Contact Information: (202) 856-1942
Original: January 2024

Centennial Airport Voluntary Noise Abatement Guidelines

*****IN ALL CASES SAFETY AND ATC INSTRUCTIONS TAKE PRECEDENCE*****

The following guidelines are recommended practices to minimizes sound levels in the vicinity of Centennial Airport.

KAPA Noise Office – 303-790-0598

Full Noise Abatement Guide: https://centennialairport.com/noise-abatement-guide

General Guidelines:

- Traffic Pattern Altitude 6,885 ft. MSL (1,000 ft. AGL)
- Avoid Noise Sensitive Areas (shown below)
- Avoid Flight Training Operations between 2200-0700L
- Make Power Changes Slowly
- Remain in Preferred Pattern Area (shown below)
- If traffic pattern volume becomes saturated causing and extended pattern North of Arapahoe Road or South of Lincoln Avenue consider returning at a less busy time to remain within the depicted traffic pattern area.

Office of Primary Responsibility (OPR): Arapahoe County Public Airport Authority
Contact Information: (303) 218-2919
Modified: June 2025