HENDERSON EXECUTIVE AIRPORT (HND) ARRIVAL ALERT

Landing South RWY 17L and RWY 17R



Pilots confuse RWY 17L and RWY 17R.

Not for Navigational Purposes
For Situational Awareness Only

HENDERSON EXECUTIVE AIRPORT (HND) ARRIVAL ALERT

Landing North RWY 35L and RWY 35R



Offset parallels. Pilots be aware that RWY 35R is 1500 feet farther down the approach than RWY 35L.

Not for Navigational Purposes
For Situational Awareness Only

Office of Primary Responsibility (OPR): ATO, Runway Safety
Contact Information: (202) 856-1942
Original: January 2024