## Calibration box 170 x 100 x 25 mm - faces A and B

Cut on the dashed lines, glue flat on the box faces. Edge labels say which face each edge meets.

**A - top (opposite the cup)** — top edge meets C, bottom edge meets D, left F, right E



**B - CUP SIDE (cup on the cross)** — top edge meets D, bottom edge meets C, left F, right E






100 mm - check before cutting (print at 100 %)

## Calibration box - sides C, D (170 x 25) and ends E, F (100 x 25)

**C - long side**

top edge meets B, bottom edge meets A, left F, right E



**D - long side**

top edge meets B, bottom edge meets A, left E, right F



**E - end**

top edge meets B, bottom edge meets A, left C, right D



**F - end**

top edge meets B, bottom edge meets A, left D, right C





100 mm - check before cutting (print at 100 %)