FULL DAQ REBOOT CHEAT SHEET

condensed from the full DAQ Operations Manual v.2.4.3

- 1. In the Run Control GUI, File -> Exit (possibly twice).
- 2. On **clondaq3**: (window is probably already open with these commands in history.)
 - > killall rcServer (twice to ensure the processes are really gone)
 - > killall rocs (twice to ensure the processes are really gone)
 - > hpsRocRebootAll.sh, wait for messages ROCS REBOOTED and TRIGGER IOC RESTARTED

Repeat if necessary, but if this fails twice, call the DAQ expert!!!!

3. In SVT Summary GUI:

Click the SVT DAQ Reboot button.

Enter the password for clasrun when prompted in the xterm that pops up.

Close xterm after completion. (takes up to 2 minutes)

Check the SVT Summary GUI for errors.

Repeat if necessary, but if this fails twice, call the DAQ expert!!!!

- 4. On **clondaq3**: (open from step 2)
 - > runcontrol -rocs

Check on all of the ROC xterms and ensure that all processes are running.

This procedure should take less than ten minutes and may be repeated but, if this fails twice, call the DAQ expert!!!!