

Task Hazard Analysis (THA) Worksheet

(See ES&H Manual Chapter 3210 Appendix T1
Work Planning, Control, and Authorization Procedure)

Click For Word

Author:	Ma	urizio Ungaro		Da	ate:	January 5, 2017		Task #: If applicable	
Complete all information. Use as many sheets as necessary									
Task Title: CLAS12 Low-Threshold Cherenkov Counter (LTCC) System					Task Location:	Hall-B			
Division:]	Physics		Departmen	ent:	Hall-B		Frequency of use:	Continuously
Lead Work	ær:								
Mitigation already in place: Standard Protecting Measures Work Control Documents		cting Measures	All workers on the LTCC s	system must	st comp	lete SAF111 (Hall B	safety training)		

Sequence of Task Steps	Task Steps/Potential Hazards	Consequence Level	Probability Level	Risk Code (before mitigation)	Proposed Mitigation (Required for Risk Code >2)	Safety Procedures/ Practices/Controls/Training	Risk Code (after mitigation
1	Energize LTCC HVs (2000 V @ 500 uA max V/I settings) - possible exposure to high voltage	М	L	2		SHV cables terminated properly at voltage supply; supply properly grounds to racks	1
2	Servicing detector components – man-lift or ladder access, potential fall hazards	Н	M	3		Harness training, man-lift training, ladder training, fall protection training	1
3	Gas Flow / Gas System Maintenance.	L	L	1		Gas is not flammable, class 0 system. LTCC Gas Manual and the Hall B Gas Controls Manual.	N
4	Gas Pressure	L	L	1		Detectors pressure and vacuum is limited to a maximum of 4"wc by the Bubbler pressure relief units.	N



Task Hazard Analysis (THA) Worksheet

(See ES&H Manual Chapter 3210 Appendix T1
Work Planning, Control, and Authorization Procedure)

Highest Risk Code before Mitigation:	3	Highest Risk Code after Mitigation:	1
--------------------------------------	---	-------------------------------------	---

When completed, if the analysis indicates that the <u>Risk Code</u> before mitigation for any steps is "medium" or higher (RC≥3), then a formal <u>Work Control Document</u> (WCD) is developed for the task. Attach this completed Task Hazard Analysis Worksheet. Have the package reviewed and approved prior to beginning work. (See <u>ES&H Manual Chapter 3310 Operational Safety Procedure Program.</u>)



Task Hazard Analysis (THA) Worksheet

(See ES&H Manual Chapter 3210 Appendix T1
Work Planning, Control, and Authorization Procedure)

Form Revision Summary

Periodic Review – 08/13/15 – No changes per TPOC

Revision 0.1 – 06/19/12 - Triennial Review. Update to format.

Revision 0.0 - 10/05/09 - Written to document current laboratory operational procedure.

ISSUING AUTHORITY	TECHNICAL POINT-OF-CONTACT	APPROVAL DATE	REVIEW DATE	REV.
ESH&Q Division	Harry Fanning	08/13/15	08/13/18	0.1

This document is controlled as an on line file. It may be printed but the print copy is not a controlled document. It is the user's responsibility to ensure that the document is the same revision as the current on line file. This copy was printed on 7/16/2021.