## Drift Gas Variables upon which alarm should -> HV (fast) shut down.

B\_BONUS\_DMS\_Temp: above threshold(?)

B\_BONUS\_GAS\_DP: below threshold

B\_BONUS\_GAS\_He\_Buffer\_Press: above threshold

B\_BONUS\_GAS\_MFC\_Flow: below threshold

B\_BONUS\_GAS\_MFC\_Flow\_Set: below threshold

B\_BONUS\_GAS\_MFC\_Temp: above threshold

B\_BONUS\_GAS\_MFC\_Valve: below threshold

B\_BONUS\_RTPC\_Press: below threshold

B\_BONUS\_RTPC\_Temp: above threshold