

Annual Safety Inspection Report

Document No: BPL-INSP-2024-0089 | Standard: OISD-STD-117

Overview

This document details the annual OISD-STD-117 compliance audit of the Crude Distillation Unit (CDU) fire protection systems.

Checklist & Findings

Check Item	Regulation	Status	Remarks
Fire Water Pump Capacity Test	OISD-117 4.2	Compliant	Pump delivered 100% capacity at 10.5 kg/cm ² .
Foam System Proportioning Test	OISD-117 4.5	Partial	Foam concentration was 2.5% (target 3%). Re-calibration required.
Deluge Valve Actuation	OISD-117 4.7	Compliant	Response time < 10 seconds.
Hydrant Flow Test	OISD-117 4.8	Non-Compliant	Hydrant H-204 pressure drop excessive. Line blockage suspected.

Corrective Actions

- Re-calibrate foam proportioner on tank T-105 by 2024-11-15.
- Flush underground fire water header leading to H-204 and retest by 2024-11-20.