

©Dr N.Paltalidis 2024

1



Design for X Topics

- Design for Manufacturing
- Design for Production
- Design for Assembly
- o Design for Recycling/Disposal
- o Design for Life Cycle
- Design for Environment

FBU5608

3

3



Design for Manufacturing (DFM)

- DFM is a design strategy that requires
 - the expertise of multiple team members
 - the use of basic design rules, guidelines, and cost models





EBU5608

4

4



Design for Manufacturing (DFM)

- DFM often results in
 - significant cost reduction
 - improvement in product quality
 - the development of cross-functional expertise within the organisation







EBU5608


5

5



Focus on manufacturability

- Focussing on how a product can be manufactured helps the design team to find **solutions** to these design **issues**:
 - Detailed design decisions can have substantial impact on product quality and cost
 - Development teams face multiple, and often conflicting, goals







EBU5608


6


6








Ö






















Unit manufacturing cost

- The 'unit manufacturing cost' is
 - the total manufacturing costs for a time period (usually a quarter or a year)
 - divided by
 - the number of units of the product manufactured during that period
- In other words 'how much it costs to make each unit'!

EBU5608

17



Manufacturing cost categories

- There are three categories of costs which make up manufacturing costs:
 - Component costs
 - Assembly costs
 - Overhead costs
 - These are shown in more detail on the next slide









EBU5608

18

17

18







Understanding manufacturing costs – assembly costs

- Assembly costs (labour, equipment & tooling)
 - Goods are generally assembled from parts
 - This process of assembly incurs labour and equipment/tooling costs





EBU5608

21

21



Understanding manufacturing costs – overhead costs

Overhead costs

- Overhead is the category used to cover all of the other costs
- There are two types of overhead cost
 - Support costs
 - 2. Indirect allocations

EBU5608

22



Understanding manufacturing costs – overhead costs (contd)

1. Support costs

- These are the costs associated with materials handling, quality assurance, purchasing, shipping, receiving, etc
- These are the support systems associated with manufacture of the product
 - these costs greatly depend on the **product design**



EBU5608

23

23

24





Queen Mary Understanding manufacturing costs - overhead costs (contd)


2. Indirect allocations


- The costs of manufacturing that **cannot** be directly linked to a particular product but which must be paid for to be in business
 - e.g. the salary of a security guard or the cost of building maintenance
- Indirect costs are **not** specifically linked to the **design** of the product
 - they are therefore are **not** relevant to **DFM** (although they do contribute to the cost of
 the product)


EBU5608 24
















Estimating the cost of assembly

- o Manual assembly costs can be **estimated** by
 - summing the estimated time of each assembly operation and
 - multiplying by a labour rate
- An example can be seen in the next slide



EBU5608

31

31



Example of the calculation for cost of assembly

- This is the assembly of an **inlet system** which is part of a car engine
- o The system is **made** up of
 - a valve a metal casting that can block the inlet
 - O-rings to seal gaps
 - a spring to release the valve
 - a cover for the whole assembly
- Assembly time includes
 - Handling time e.g. picking up the components
 - Insertion time e.g. joining the components together





[4]


EBU5608


32


32
















38



39





Estimating the overhead costs (cont.)

- Overhead rates are typically applied to one or two cost drivers
 - Cost drivers are parameters of the product which are directly measurable
- o Common cost drivers are
 - the cost of any purchased materials
 - the cost of assembly labour
 - the number of hours of equipment time the product consumes
- Overhead charges are added in **proportion** to the value of the drivers

EBU5608

41




Estimating the overhead costs - an example


- The overhead rate for purchased materials for a product is 10% (of the purchased cost)
- The overhead rate for assembly labour for the product is 80% of the labour costs
- A product containing \$100 of purchased components and \$10 of assembly labour


Item	Value	Overhead rate	Overhead cost
Component costs	\$100	10%	\$10
Labour costs	\$10	80%	\$8
Total overhead costs			\$18


EBU5608 42


42






















Step 3 – Reduce the costs of assembly

- 'Design for Assembly' (DFA) places an emphasis on identifying ways in which assembly costs can be reduced
- o The key ideas of DFA are to:
 - Minimize parts count
 - Maximize the ease of handling parts
 - Maximize the ease of inserting parts

FBU5608

- o The **benefits** of DFA are:
 - Lower labour costs
 - Other indirect benefits



51



Design for Assembly rules

Example set of DFA guidelines from a computer manufacturer

- Minimize parts count
- 2. Encourage modular assembly
- 3. Eliminate adjustments
- 4. Eliminate cables
- 5. Use self-fastening parts
- Use self-locating parts
- Eliminate reorientation
- 8. Facilitate parts handling
- Specify standard parts



52

52

©Dr N.Paltalidis 2024 26

EBU5608



Design for Assembly

oKey ideas of DFA:

- Minimise parts count
- Maximise the ease of handling parts
- Maximise the ease of inserting parts

Benefits of DFA

- Lower labor costs
- Other indirect benefits
- Popular software developed by Boothroyd and Dewhurst.
 - http://www.dfma.com

EBU5608

53

53





Maximise Ease of Assembly

- Part is inserted from the top of the assembly
- o Part is self-aligning
- Part does not need to be oriented
- o Part requires only one hand for assembly
- Part requires no tools
- Part is assembled in a single, linear motion
- Part is secured immediately upon insertion

EBU5608 54

54







Step 4 – Reduce the costs of supporting production

 As a result of reducing the costs of components and the costs of assembly, the team may also achieve reductions in the demands placed on the production support functions

FBU5608

57


57



Step 4 – Reduce the costs of supporting production



- Examples
 - A reduction in the number of parts reduces the demands on inventory management









EBU5608

58







Step 5 - Consider the impact of DFM decisions on other factors

- The impact of DFM on development time
 - DFM has a focus on cost reduction, which usually includes the design of individual components to reduce steps in production and therefore cost
 - However, if these design decisions would increase development time and delay the release, then the priorities of the organisation will have to be considered



EBU5608

61

61



Step 5 - Consider the impact of DFM decisions on other factors


- The impact of DFM on product quality
 - Will any decision stemming from DFM affect the product's quality?
 - The majority of improvements to the manufacturing process will usually result in an improvement to the quality of the product
 - In most cases a reduction in components that require subsequent integration and testing improves quality





 However, this is not always the case and decisions regarding trade-offs will need to be taken in line with the organisation's product strategies


EBU5608 62

62











References

- Product Design and Development, Karl T Ulrich and Steven D Eppinger, International Edition (3rd) McGraw-Hill, 2003, pg 213
- 2. .. Pg. 214
- 3. .. Pg. 218
- 4. .. Pg. 219
- 5. <u>http://www.tomshardware.com/news/apple-battery-patent-ipad-iphone,14155.html</u>
- 6. <u>http://rainwillow.com/2012/04/integrated-versus-modular-architectures/</u>

EBU5608 68

68