	Partner 1 Email:		Partner 2 Email:		Partner 3 Email:
Partner 1 Name:	jeremymills@berkeley.	Partner 2 Name: Louie	louiejoshualabata@ Partner 3 Name:	Partner 3 Name:	misk@berkeley.
Jeremy Mills	edu	Labata	berkeley.edu	Misk Almomen	edu
Inctrictions					

not purchase it. For any approved Amazon or Adafruit parts, leave Digi-key and Mouser Part# columns blank like the example. For approved Amazon par Product Information Section) for Manufacturer Part # in the format "Amazon - #######". For approved Adafruit parts, put the Product ID for Manufac Fill in the cells with the YELLOW highlight. Do not edit red cells. WE WILL ADJUST THE MULTIPLIER TO ACCOUNT FOR MULTIPLE BOARDS, YOU SHOULD NC OR the Mouser Part #, DO NOT fill out both. Choose the cheapest distributor that has the part in stock. If the part is not in stock by the time we order par "Adafruit - ###".

Qty					Reference	ence
(for 1 board)	Manufacturer Part #	Digi-key Part#/SKU	Mouser Part#/SKU Price/unit (\$)	Price/unit (\$)	Purchase URL Designator	nator
	1 LM2940IMP-15/NOPB	LM2940IMP-15/NOPBCT-NE		0,	\$1.84 https://www.digik_U1	
	1 LM7915CT/NOPB-ND	LM7915CT/NOPB-ND		0,	\$1.67 https://www.digik_U2	
	1 AP63203WU-7	AP63203WU-7DICT-ND		0,	\$1.32 https://www.digik_U3	
	1 MDB10S	MDB10SFSCT-ND		0,	\$0.53 https://www.digik_D1	
	1 BV201S15006	3388-BV201S15006-ND		0,	\$3.88 https://www.digik_T1	
	1 860010672004	860010672004 732-8656-1-ND		0,	\$0.10 https://www.digik C1	
	3 860020372002	860020372002 732-8789-1-ND		0,	\$0.10 https://www.digik C2, C32, C33	32, C33
	1 860020672006	860020672006 732-8852-1-ND		Ο,	\$0.10 https://www.digik C3	
	1 860020672005	860020672005 732-8851-1-ND		0,	\$0.10 https://www.digik_C4	
	2 GMC21X5R226M16NT	4713-GMC21X5R226M16N		0,	\$0.16 https://www.digik C5, C6	"0
	1 CL10A106MQ8NNNC	1276-1119-1-ND		0,	\$0.10 https://www.digik C35	
	1 CDRH5D28NP-3R0NC	308-2177-1-ND		0,	\$0.48 https://www.digik_L1	
	1 AP63205WU-7	AP63205WU-7DICT-ND		0,	\$1.32 https://www.digik_U6	
	1 WCLA3225V1-4R7-R	283-WCLA3225V1-4R7-RCT		0,	\$0.32 https://www.digik_L2	
	1 OPA2134UA/2K5	296-22024-1-ND		V)	\$5.33 https://www.digik_U4	
	1 LM1875T/NOPB	LM1875T/NOPB-ND		V)	\$1.89 https://www.digik_U5	
	3 GMC10X5R106M10NT	4713-GMC10X5R106M10N		V)	\$0.10 https://www.digik C7, C8, C10	3, C10
	1 C0603C472K4RECAUTO	399-17879-1-ND		0,	\$0.13 https://www.digik_C9	
	7 CC0603KRX7R7BB104	311-1088-1-ND		V)	\$0.10 https://www.digik C13, C15, C31, (:15, C31, (
	1 CL10A475KP8NNNC	1276-1044-1-ND		V)	\$0.10 https://www.digik C11	
	1 CL10B333KC8WPNC	1276-CL10B333KC8WPNCC		V)	\$0.11 https://www.digik_C17	
	3 860040674004	860040674004 732-9187-1-ND		V)	\$0.34 https://www.digik C12, C14, C16	314, C16
	1 ERJ-3EKF1000V	P100HCT-ND		V)	\$0.10 https://www.digik_R2	
	1 RC0603FR-0747KL	311-47.0KHRCT-ND		•	\$0.10 https://www.digik_R3	

3 ERA-3AEB122V	P1.2KDBCT-ND	\$0.14 https://www.digik_R4, R8, R10
1 RMCF0603JT10K0	RMCF0603JT10K0CT-ND	\$0.10 https://www.digik_R5
1 RC0603FR-071ML	311-1.00MHRCT-ND	\$0.10 https://www.digik_R6
1 ERA-3AEB223V	P22KDBCT-ND	\$0.14 https://www.digik_R7
7 ERJ-3EKF2002V	P20.0KHCT-ND	\$0.10 https://www.digik R9, R11, R12, R
1 RC0603FR-071KL	311-1.00KHRCT-ND	\$0.10 https://www.digik_R1
1 CTW-3414-204SE	2223-CTW-3414-204SE-ND	\$8.30 https://www.digik_LS1
1 PJ-002B	CP-002B-ND	\$0.66 https://www.digik_J1
14 CL10B105KP8NNNC	1276-1946-1-ND	\$0.10 https://www.digik C18, C19, C20, (
1 RMCF0603JT10K0	RMCF0603JT10K0CT-ND	\$0.10 https://www.digik_R22
1 PCM5102APWR	296-36707-1-ND	\$4.95 https://www.digik_U12
1 PCM1808PWR	296-26307-1-ND	\$1.66 https://www.digik_U13
1 ESP32-S2-SOLO-2-N4	1965-ESP32-S2-SOLO-2-N4[\$2.40 https://www.digik_U10
1 10118193-0001LF	609-4616-1-ND	\$0.54 https://www.digik_J2
2 RC0603FR-075K1L	311-5.10KHRCT-ND	\$0.10 https://www.digik R20, R21
3 AOZ9510QI	785-AOZ9510QICT-ND	\$1.56 https://www.digik_U7, U8, U9
3 D1WEL0805MR006F-T5	4463-D1WEL0805MR006F-	\$0.28 https://www.digik R13, R16, R19