





[PIN]	PB0 [12]	PB1 [11]	PB2 [10]	PB3 [5]	PB4 [8]	PB5 [7]	PB6 [6]	PB7 [9]	Restore [3]	shift lock [21]
PA0 [13]	DEL	Return	\leftrightarrow	F7	F1	F3	F5	1		
PA1 [19]	3	W	A	4	Z	S	E	Left Shift		
PA2 [18]	5	R	D	6	C	F	T	X		
PA3 [17]	7	Y	G	8	В	Н	U	V		
PA4 [16]	9	I	J	0	M	K	O	N		
PA5 [15]	+	P	L	-		:	(a)	,		
PA6 [14]	£	*	;	CLR	Right Shift	=	1	/		
PA7 [20]	1	←	CTRL	2	Space	Ç.	Q	STOP		
GND [1,23,24]									RESTORE	Shift lock
				1.						

n [2],[25] NC n [4] + 5 Volt Shift lock led [22] GND [1,23,24]

C128	C	1	2	3 O	o	C	5	6	7	o 8	o ⁹	O	⁰ C	11 C	12	¹³
~		O ₁₄	0)	0	0	0	0	C) ()	0	O ₂₄	0	

[PIN]	PB0 [12]	PB1 [11]	PB2 [10]	PB3 [5]	PB4 [8]	PB5 [7]	PB6 [6]	PB7 [9]	Restore [3]
PA0 [13]	DEL	Return	\leftrightarrow	F7	F1	F3	F5	‡	
PA1 [19]	3	W	A	4	Z	S	E	Left Shift	
PA2 [18]	5	R	D	6	C	F	T	X	
PA3 [17]	7	Y	G	8	В	Н	U	V	
PA4 [16]	9	I	J	0	M	K	O	N	
PA5 [15]	+	P	L	-		:	(a)	,	
PA6 [14]	£	*	;	CLR	Right Shift	=	1	/	
PA7 [20]	1	←	CTRL	2	Space	(k	Q	STOP	
K0 [21]	help	8	5	tab	2	4	7	1	
K1 [22]	esc	+	-	line feed	enter	6	9	3	
	alt	0		A	▼	◀	•	no scroll	
GND [1]									RESTORE

switch between [9] and [19] shift lock switch between [1] and [24] 40/80 col. pin [2] KEY pin [4] NC

switch between [1] and [25] caps lock pin [21],[22] and [23] (K0,K1 and K2) are handled by VIC IIe

≤	[PIN]	PB0 [12]	PB1 [11]	PB2 [10]	PB3 [5]	PB4 [8]	PB5 [7]	PB6 [6]	PB7 [9]	Restore [3]
	PA0 [13]	DEL	Return	\leftrightarrow	F7	F1	F3	F5	1	
	PA1 [19]	3	W	A	4	Z	S	E	Left Shift	
	PA2 [18]	5	R	D	6	C	F	T	X	
	PA3 [17]	7	Y	G	8	В	Н	U	V	
	PA4 [16]	9	I	J	0	M	K	O	N	
	PA5 [15]	+	P	L	-		:	(a)	,	
	PA6 [14]	£	*	;	CLR	Right Shift	=	1	/	
	PA7 [20]	1	←	CTRL	2	Space	Ç.	Q	STOP	
	GND [1]									RESTORE

pin [2] KEY (NC) pin [4] + 5 Volt

[PIN]	K0 [18]	K1 [15]	K2 [14]	K7 [3]	K4 [7]	K5 [9]	K6 [10]	K3 [17]
P7 [6]	1	CLR	CTRL	Run Stop	Space	(k	Q	2
P0 [8]	3	W	A	Shift	Z	S	Е	4
P2 [12]	5	R	D	X	C	F	T	6
P1 [11]	7	Y	G	V	В	Н	U	8
P3 [13]	9	I	J	N	M	K	О	0
P6 [1]	▼	P	L			:	-	A
P4 [16]	◀	*	ļ;	/	ESC	=	+	
P5 [19]	Del	Return	£	(a)	F1	F2	F3	Help

pin [2] KEY (NC) pin [5],[20] NC pin [4] + 5 Volt 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17

4											
\bigcirc	[PIN]	K0 [17]	K1 [14]	K2 [13]	K7 [2]	K4 [6]	K5 [8]	K6 [9]	K3 [16]		
11	P7 [5]	1	CLR	CTRL	Run Stop	Space	(k	Q	2		
6	P0 [7]	3	W	A	Shift	Z	S	E	4		
	P2 [11]	5	R	D	X	C	F	T	6		
	P1 [10]	7	Y	G	V	В	Н	U	8		
	P3 [12]	9	I	J	N	M	K	O	0		
	P6 [1]	▼	P	L			:	-	A		
	P4 [15]	◀	*	;	/	ESC	=	+	>		
	P5 [18]	Del	Return	£	(a)	F1	F2	F3	Help		
	pin [4] + 5 Vo	lt			[4]—[3]						