


$R_L = 220\Omega$




 $R_L = 470\Omega$




 $R_L = 680\Omega$




 $R_L = 820\Omega$




 $R_L = 1000\Omega$




 $R_L = 1500\Omega$




 $R_L = 1800\Omega$



 $R_L = 2200\Omega$



 $R_L = 3900\Omega$



 $R_L = 4700\Omega$

