



D=40 | Vary: x/Diameter

(Top≈1924/2566 rpmM tip≈0.118/0.158; Bottom≈1924/2566 rpm, M_tip≈0.118/0.158)




D=40 | Vary: x/Diameter

(Top≈1924/2566 rpmM tip≈0.118/0.158; Bottom≈1924/2566 rpm, M_tip≈0.118/0.158)




D=40 | Vary: x/Diameter

(Top≈1924/2566 rpmM_tip≈0.118/0.158; Bottom≈1924/2566 rpm, M_tip≈0.118/0.158)




D=13 | Vary: x/Diameter

(Top≈5864/7819 rpmM tip≈0.117/0.156; Bottom≈5864/7819 rpm, M_tip≈0.117/0.156)




D=13 | Vary: x/Diameter

(Top≈5864/7819 rpmM tip≈0.117/0.156; Bottom≈5864/7819 rpm, M_tip≈0.117/0.156)




D=13 | Vary: x/Diameter

(Top≈5864/7819 rpmM tip≈0.117/0.156; Bottom≈5864/7819 rpm, M_tip≈0.117/0.156)



D=6 | Vary: x/Diameter

(Top≈12780/17040 rpmM_tip≈0.118/0.157; Bottom≈12780/17040 rpm, M_tip≈0.118/0.157)



D=6 | Vary: x/Diameter

(Top≈12780/17040 rpmM_tip≈0.118/0.157; Bottom≈12780/17040 rpm, M_tip≈0.118/0.157)



D=6 | Vary: x/Diameter

(Top≈12780/17040 rpmM tip≈0.118/0.157; Bottom≈12780/17040 rpm, M_tip≈0.118/0.157)

