Release Notes

Axiocam USB 3.0 SDK

Version 1.62

2016-02-22

Supported Platforms:

- Linux x64
- Windows 7 x64

For more information see also (included in this SDK):

- README.TXT
- AxioCam_SDK_USB_3.0_HTML1.62.zip

The following list shows the history of changes for the Axiocam USB 3.0 SDK.

Axiocam SDK - History

Release: 1.43		Date: 2015-03-06
Ticket	Description	
#1063	Common Developer SDK for ZEN, AxioVision and external users	

	Release: 1.44	
Ticket	Description	
#1025	WinUSB Basis Treiber für Axiocam FTDI Chip	
#1096	Bitstream Programming in Superspeed	
#1099	Support Axiocam 512c	
#1100	TileAdjustment Memory Allocation Error on Stack	
#1101	Support for Suspend Mode for USB 3,0 - LED off during suspend	
#1103	Power Sharing does not work between USB-Ports	
#1105	Support of Axiocam 702	

Release: 1.45		
Ticket	D	escription
#1119	Signed Drivers for Windows	
#1133	Adaption for IMX174 - DLL Fixes for Black-Ref/Blemishes	
#1135	SDK-Documentation review comments from SDK Beta-tester incorporated	

	Release: 1.46	
Ticket	D	escription
#1123	Adaption for IMX174 - SW binning	

#1139	Fixed McammGetCCDPixelDistance for 512 and 702
#1140	Blackreference fixes for Axiocam 702

Release: 1.47		
Ticket	Description	
#1052	Adaption for IMX174 - implement 2x horizontal binning in HW	
#1054	Adaption for IMX174 - HDR Image	
#1083	Adaption for IMX174 – dithering	
#1123	Adaption for IMX174 - SW binning	
#1126	Adaption IMX174 - non linear blemish pixels	
#1134	Adaption IMX174 - gcam non linear blemish pixels	
#1138	Adaption for IMX174 - fill histogramm gaps in compressed mode	
#1141	Triple-Blemishes	
#1148	No Discard Mode for HDR	
#1149	New Interface LineFlickerSuppression configuration	tion

	Release: 1.48	
Ticket	D	escription
#1150	DLL API Extensions for CMOS cameras	
#1153	Adaptions for IMX174 - offset pixels	

	Release: 1.49	Date: 2015-07-27
Ticket	Description	
#1084	Adaptions for IMX174 – Anti-Glow	
#1151	Adaptions for IMX174 - fast readout for smaller H-ROIs	
#1156	Adaption for IMX174 - enable compression indication	
#1160	Adaption for IMX174 - disable lineAdjustment for linear mode	
#1161	Adaptions for IMX174 - HDR exposure time inexact	
#1163	Performance Improvement 8 Bit Compression	

	Release: 1.50	Date: 2015-08-26
Ticket	Description	
#1169	Crash of Axiocam 702 mono after changing Roi Parameter	
#1178	LineFlicker Optimization – HotSpot	
#1180	Last Image incomplete Axiocam 702	

	Release: 1.51	Date: 2015-09-16
Ticket	Description	
#1157	Min frame-delay for high image rates for CMOS cameras	
#1206	8 Bit Compression with Axiocam 512c does not work	

	Release: 1.52	Date: 2015-10-07
Ticket	Description	
#1245	Endless DLL-Start Loop if one camera has a permanent error	
#1246	SDK-Update for Axiocam 512/702	

	Release: 1.53	Date: 2015-10-22
Ticket	Description	
#1108	Persistent USB3 in low power mode on HP Laptop	
#1245	Endless DLL-Start Loop if one camera has a permanent error	
#1251	HDR mode - sporadically wrong exposure time	
#1254	HDR Acquisition fails with external Trigger	
#1255	Race Condition with SW Trigger and ContShot	
#1257	DLL-Crash if camera connected during shutdown	
#1258	Blackreference Axiocam 512c cannot be defined - image too bright	

Release: 1.54		Date: 2015-11-08
Ticket	Description	
#1271	No logging of IP-Only Session if logfile name is changed via Session-Properties	
#1272	MCammIs8BitCompressionFaster returns wrong result for small ROIs for Axiocam 702m	
#1273	Extra Images after StopAcquisition in HDR mode	

Release: 1.55		Date: 2015-11-15
Ticket	Description	
#1279	Gaps in image number in HDR mode + trigger	
#1280	Wrong exposure/gain after HDR mode switch - triggered SingleShot	

Release: 1.61		Date: 2016-01-29
Ticket	Description	
#1325	Optimizing Image Throughput in Camera	
#1329	Implausible frequent reports of INTR_ACQ_TIMEOUT during axiftest	
#1337	Implement new capability Interface: query supported features of each camera model	

Release: 1.62		Date: 2016-02-17
Ticket	Description	
#1344	Cooling sporadically does not work for Axiocam 702m	
#1346	Stop ContShot sporadically lasts 3 seconds	
#1277	Wrong exposure time in HDR + sw/hw trigger for Continous Shot and SingleShot	
#1348	Adaption to new ZEN 2.3 log path for mcam	
#1355	Support of camera buffering combined with fully processed images	
#1357	USB 3.0 Driver Update (INF only)	
#1358	Green Camera Main LED is off instead of "green" in USB 2.0 mode	
#1360	702m - HDR Mode Issue	