

1. Update All Relevant Functions

- Ensure that all surface creation functions (e.g., rear spar surfaces, stringer surfaces, etc.) conform to the **top-left, counterclockwise order**.
- Adjust the order in:
 - surface_coords array for calculations.
 - Plotting logic to maintain the correct visualization.

Example:

matlab

Copy code

```
surface_coords = [  
    node_1.x, node_1.y; % Top-left  
    node_2.x, node_2.y; % Lower-left  
    node_3.x, node_3.y; % Lower-right  
    node_4.x, node_4.y; % Upper-right  
];
```

2. Update Documentation

Include the order standard in your documentation to ensure consistency:

- **Order of Nodes:** All quadrilateral surfaces follow the **top-left, counterclockwise order: node_1 → node_2 → node_3 → node_4**.
 - **Usage Context:** Mention that this standard is used for:
 - Surface creation.
 - Area and aspect ratio calculations.
 - Visualization (e.g., plotting).
-

3. Update Plotting Functions

Adjust plotting functions to respect the node order:

- Ensure that quadrilateral surfaces are plotted using the same **top-left, counterclockwise order**.

- Example of correctly ordered plotting:

matlab

Copy code

```
fill(surface_coords(:, 1), surface_coords(:, 2), 'cyan', 'FaceAlpha', 0.3, 'EdgeColor',  
'b', 'LineWidth', 1.2);
```

4. Consistency Check

- **Area Calculation:** Verify that the calculated areas match expected results.
- **Aspect Ratio:** Validate that aspect ratios reflect the correct geometric proportions.

5. Add to Thesis Framework

Incorporate the documentation into your thesis:

- Create a section explaining the **surface node order standard** in detail.
- Include diagrams or examples illustrating the order for both quadrilaterals and triangles.

6. Communication Notes

When discussing with collaborators or referring to these surfaces:

- Clearly mention that all surfaces adhere to the **top-left, counterclockwise order**.
- If providing tables or diagrams, highlight the order visually (e.g., use labeled node positions in diagrams).