```
__CONFIG _CP_OFF & _WDT_OFF & _XT_OSC & _PWRTE_ON
LIST P=PIC16F84A
#INCLUDE <P16F84A.INC>
RESET ORG 0X00
  GOTO Inicio
 ORG 0X05
Inicio
  BSF STATUS, RPO
  MOVLW b'11111'
  MOVWF TRISA
  CLRF TRISB
  BCF STATUS, RPO
  GOTO Operacion
Operacion
  MOVF PORTA, W
 ADDWF PORTA,W
  ADDWF PORTA,W
 ADDWF PORTA,W; Ya que no hay instruccion que multiplique
  ADDWF PORTA,W ;Sumo el numero ingresado 5 veces
 XORLW b'11111111'
  MOVWF PORTB
  GOTO Operacion
  End
```



