Métricas de Sensores

==== Sensor: 1_AIT_001_PV =====

Métrica	Valor
Media	167.64
Desviacion Tipica	13.06
Minimo	0.00
P25	156.47
P75	174.66
Maximo	214.31
varianza	170.62
skew	1.09
kurt	2.17

==== Sensor: 1_AIT_002_PV =====

Métrica	Valor
Media	0.62
Desviacion Tipica	0.06
Minimo	0.00
P25	0.58
P75	0.66
Maximo	2.02
varianza	0.00
skew	1.19
kurt	14.42

==== Sensor: 1_AIT_003_PV =====

Métrica	Valor
Media	11.75
Desviacion Tipica	0.18
Minimo	0.00
P25	11.65
P75	11.84
Maximo	12.18
varianza	0.03
skew	-13.89
kurt	877.68

==== Sensor: 1_AIT_004_PV =====

Métrica	Valor
Media	487.81
Desviacion Tipica	23.16
Minimo	0.00
P25	475.28
P75	503.92
Maximo	526.53
varianza	536.51
skew	-1.42
kurt	10.65

==== Sensor: 1_AIT_005_PV =====

Métrica	Valor
Media	0.30
Desviacion Tipica	0.05

Minimo	0.21
P25	0.26
P75	0.34
Maximo	0.42
varianza	0.00
skew	0.11
kurt	-1.09

==== Sensor: 1_FIT_001_PV =====

Métrica	Valor
Media	0.52
Desviacion Tipica	0.85
Minimo	0.00
P25	0.00
P75	1.86
Maximo	2.07
varianza	0.73
skew	1.02
kurt	-0.96

===== Sensor: 1_LS_001_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00

Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

===== Sensor: 1_LS_002_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 1_LT_001_PV =====

Métrica	Valor
Media	56.92
Desviacion Tipica	11.57
Minimo	0.03
P25	48.84
P75	62.92
Maximo	100.21
varianza	133.97
skew	0.59

==== Sensor: 1_MV_001_STATUS =====

Métrica	Valor
Media	1.27
Desviacion Tipica	0.45
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.20
skew	0.99
kurt	-0.90

==== Sensor: 1_MV_002_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 1_MV_004_STATUS =====

Métrica	Valor
Media	1.28
Desviacion Tipica	0.45
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.20
skew	0.93
kurt	-0.99

===== Sensor: 1_P_001_STATUS =====

Métrica	Valor
Media	1.27
Desviacion Tipica	0.45

Minimo	1.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.20
skew	1.01
kurt	-0.97

==== Sensor: 1_P_002_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 1_P_003_STATUS =====

Métrica	Valor
Media	1.27
Desviacion Tipica	0.45
Minimo	1.00
P25	1.00
P75	2.00

Maximo	2.00
varianza	0.20
skew	1.01
kurt	-0.97

==== Sensor: 1_P_004_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 1_P_005_STATUS =====

Métrica	Valor
Media	1.23
Desviacion Tipica	0.42
Minimo	1.00
P25	1.00
P75	1.00
Maximo	2.00
varianza	0.18
skew	1.30

kurt	-0.32
------	-------

==== Sensor: 1_P_006_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_DPIT_001_PV =====

Métrica	Valor
Media	2517.61
Desviacion Tipica	131.01
Minimo	0.00
P25	2505.03
P75	2572.38
Maximo	2695.93
varianza	17162.54
skew	-8.09
kurt	98.97

Métrica	Valor
Media	63.48
Desviacion Tipica	36.96
Minimo	8.21
P25	25.45
P75	100.00
Maximo	100.00
varianza	1365.84
skew	-0.12
kurt	-1.86

==== Sensor: 2_FIC_101_PV =====

Métrica	Valor
Media	0.12
Desviacion Tipica	0.14
Minimo	0.02
P25	0.04
P75	0.14
Maximo	3.03
varianza	0.02
skew	5.22
kurt	51.58

===== Sensor: 2_FIC_101_SP =====

Métrica	Valor
Media	0.22
Desviacion Tipica	0.12

Minimo	0.09
P25	0.11
P75	0.30
Maximo	0.51
varianza	0.01
skew	0.71
kurt	-0.67

==== Sensor: 2_FIC_201_CO =====

Métrica	Valor
Media	64.13
Desviacion Tipica	37.36
Minimo	8.70
P25	25.43
P75	100.00
Maximo	100.00
varianza	1396.01
skew	-0.15
kurt	-1.88

==== Sensor: 2_FIC_201_PV =====

Métrica	Valor
Media	0.11
Desviacion Tipica	0.12
Minimo	0.02
P25	0.05
P75	0.13

Maximo	2.63
varianza	0.01
skew	4.51
kurt	43.34

===== Sensor: 2_FIC_201_SP =====

Métrica	Valor
Media	0.21
Desviacion Tipica	0.12
Minimo	0.08
P25	0.11
P75	0.27
Maximo	0.52
varianza	0.01
skew	0.98
kurt	-0.13

==== Sensor: 2_FIC_301_CO =====

Métrica	Valor
Media	67.29
Desviacion Tipica	38.47
Minimo	5.47
P25	23.93
P75	100.00
Maximo	100.00
varianza	1480.06
skew	-0.38

kurt	-1.78
------	-------

===== Sensor: 2_FIC_301_PV =====

Métrica	Valor
Media	0.10
Desviacion Tipica	0.12
Minimo	0.02
P25	0.04
P75	0.12
Maximo	2.80
varianza	0.01
skew	5.14
kurt	53.54

===== Sensor: 2_FIC_301_SP =====

Métrica	Valor
Media	0.21
Desviacion Tipica	0.12
Minimo	0.06
P25	0.12
P75	0.29
Maximo	0.52
varianza	0.01
skew	0.93
kurt	-0.22

Métrica	Valor
Media	58.47
Desviacion Tipica	37.67
Minimo	5.25
P25	22.59
P75	100.00
Maximo	100.00
varianza	1418.66
skew	0.10
kurt	-1.87

===== Sensor: 2_FIC_401_PV =====

Métrica	Valor
Media	0.13
Desviacion Tipica	0.14
Minimo	0.02
P25	0.04
P75	0.19
Maximo	2.66
varianza	0.02
skew	4.98
kurt	51.99

===== Sensor: 2_FIC_401_SP =====

Métrica	Valor
Media	0.21
Desviacion Tipica	0.11

Minimo	0.08
P25	0.12
P75	0.27
Maximo	0.51
varianza	0.01
skew	0.96
kurt	0.07

==== Sensor: 2_FIC_501_CO =====

Métrica	Valor
Media	61.67
Desviacion Tipica	39.47
Minimo	4.79
P25	20.76
P75	100.00
Maximo	100.00
varianza	1558.21
skew	-0.12
kurt	-1.91

===== Sensor: 2_FIC_501_PV =====

Métrica	Valor
Media	0.11
Desviacion Tipica	0.13
Minimo	0.02
P25	0.04
P75	0.13

Maximo	3.10
varianza	0.02
skew	4.80
kurt	49.04

===== Sensor: 2_FIC_501_SP =====

Métrica	Valor
Media	0.22
Desviacion Tipica	0.15
Minimo	0.09
P25	0.11
P75	0.26
Maximo	1.15
varianza	0.02
skew	2.11
kurt	8.25

==== Sensor: 2_FIC_601_CO =====

Métrica	Valor
Media	65.06
Desviacion Tipica	38.78
Minimo	4.20
P25	23.14
P75	100.00
Maximo	100.00
varianza	1503.74
skew	-0.26

kurt	-1.86
------	-------

===== Sensor: 2_FIC_601_PV =====

Métrica	Valor
Media	0.10
Desviacion Tipica	0.12
Minimo	0.02
P25	0.02
P75	0.11
Maximo	3.16
varianza	0.02
skew	4.52
kurt	43.66

===== Sensor: 2_FIC_601_SP =====

Métrica	Valor
Media	0.22
Desviacion Tipica	0.13
Minimo	0.08
P25	0.11
P75	0.31
Maximo	0.52
varianza	0.02
skew	0.78
kurt	-0.69

Métrica	Valor
Media	0.51
Desviacion Tipica	0.94
Minimo	0.00
P25	0.00
P75	0.00
Maximo	2.31
varianza	0.89
skew	1.30
kurt	-0.30

===== Sensor: 2_FIT_002_PV =====

Métrica	Valor
Media	0.28
Desviacion Tipica	0.27
Minimo	0.00
P25	0.00
P75	0.52
Maximo	1.17
varianza	0.07
skew	0.36
kurt	-1.24

==== Sensor: 2_FIT_003_PV =====

Métrica	Valor
Media	0.21
Desviacion Tipica	0.52

Minimo	0.00
P25	0.00
P75	0.00
Maximo	5.15
varianza	0.28
skew	2.93
kurt	10.85

==== Sensor: 2_FQ_101_PV =====

Métrica	Valor
Media	0.12
Desviacion Tipica	0.14
Minimo	0.02
P25	0.04
P75	0.14
Maximo	2.96
varianza	0.02
skew	5.22
kurt	51.75

==== Sensor: 2_FQ_201_PV =====

Métrica	Valor
Media	0.11
Desviacion Tipica	0.12
Minimo	0.02
P25	0.05
P75	0.13

Maximo	2.61
varianza	0.01
skew	4.49
kurt	42.88

==== Sensor: 2_FQ_301_PV =====

Métrica	Valor
Media	0.10
Desviacion Tipica	0.12
Minimo	0.02
P25	0.04
P75	0.12
Maximo	2.80
varianza	0.01
skew	5.17
kurt	54.32

==== Sensor: 2_FQ_401_PV =====

Métrica	Valor
Media	0.13
Desviacion Tipica	0.14
Minimo	0.02
P25	0.04
P75	0.19
Maximo	2.66
varianza	0.02
skew	4.96

kurt	51.61
------	-------

===== Sensor: 2_FQ_501_PV =====

Métrica	Valor
Media	0.11
Desviacion Tipica	0.13
Minimo	0.02
P25	0.04
P75	0.13
Maximo	3.10
varianza	0.02
skew	4.78
kurt	48.69

==== Sensor: 2_FQ_601_PV =====

Métrica	Valor
Media	0.10
Desviacion Tipica	0.12
Minimo	0.02
P25	0.02
P75	0.11
Maximo	3.12
varianza	0.02
skew	4.54
kurt	44.33

===== Sensor: 2_LS_001_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

===== Sensor: 2_LS_002_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

===== Sensor: 2_LS_101_AH =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.04

Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	22.17
kurt	491.36

===== Sensor: 2_LS_101_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.06
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	15.58
kurt	241.18

===== Sensor: 2_LS_201_AH =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.04
Minimo	0.00
P25	0.00
P75	0.00

Maximo	1.00
varianza	0.00
skew	26.66
kurt	710.98

===== Sensor: 2_LS_201_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.06
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	18.00
kurt	322.49

==== Sensor: 2_LS_301_AH =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.06
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	17.77

kurt	314.43
------	--------

===== Sensor: 2_LS_301_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.05
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	18.64
kurt	346.38

==== Sensor: 2_LS_401_AH =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.04
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	23.85
kurt	569.08

===== Sensor: 2_LS_401_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.06
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	15.98
kurt	254.03

===== Sensor: 2_LS_501_AH =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.05
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	19.26
kurt	370.27

===== Sensor: 2_LS_501_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.05

Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.00
skew	18.39
kurt	337.12

===== Sensor: 2_LS_601_AH =====

Métrica	Valor
Media	0.01
Desviacion Tipica	0.09
Minimo	0.00
P25	0.00
P75	0.00
Maximo	1.00
varianza	0.01
skew	10.62
kurt	110.82

===== Sensor: 2_LS_601_AL =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.06
Minimo	0.00
P25	0.00
P75	0.00

Maximo	1.00
varianza	0.00
skew	17.88
kurt	318.32

==== Sensor: 2_LT_001_PV =====

Métrica	Valor
Media	69.68
Desviacion Tipica	0.60
Minimo	68.51
P25	69.19
P75	70.08
Maximo	71.54
varianza	0.36
skew	0.51
kurt	-0.40

==== Sensor: 2_LT_002_PV =====

Métrica	Valor
Media	75.16
Desviacion Tipica	4.00
Minimo	33.11
P25	72.33
P75	77.93
Maximo	83.13
varianza	16.03
skew	-1.82

kurt	12.21
------	-------

==== Sensor: 2_MCV_007_CO =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_MCV_101_CO =====

Métrica	Valor
Media	10.93
Desviacion Tipica	15.26
Minimo	0.00
P25	0.00
P75	20.79
Maximo	100.00
varianza	232.82
skew	2.22
kurt	8.28

Métrica	Valor
Media	12.12
Desviacion Tipica	17.03
Minimo	0.00
P25	0.00
P75	20.69
Maximo	100.00
varianza	290.15
skew	2.52
kurt	9.15

==== Sensor: 2_MCV_301_CO =====

Métrica	Valor
Media	17.07
Desviacion Tipica	21.03
Minimo	0.00
P25	0.00
P75	25.43
Maximo	100.00
varianza	442.28
skew	1.93
kurt	4.63

==== Sensor: 2_MCV_401_CO =====

Métrica	Valor
Media	10.46
Desviacion Tipica	15.77

Minimo	0.00
P25	0.00
P75	19.58
Maximo	100.00
varianza	248.69
skew	2.47
kurt	9.44

==== Sensor: 2_MCV_501_CO =====

Métrica	Valor
Media	13.38
Desviacion Tipica	17.00
Minimo	0.00
P25	0.00
P75	24.65
Maximo	100.00
varianza	289.04
skew	1.72
kurt	4.89

==== Sensor: 2_MCV_601_CO =====

Métrica	Valor
Media	17.44
Desviacion Tipica	22.88
Minimo	0.00
P25	0.00
P75	26.72

Maximo	100.00
varianza	523.59
skew	1.85
kurt	3.74

==== Sensor: 2_MV_001_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_MV_002_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00

==== Sensor: 2_MV_003_STATUS =====

Métrica	Valor
Media	1.22
Desviacion Tipica	0.43
Minimo	0.00
P25	1.00
P75	1.00
Maximo	2.00
varianza	0.19
skew	1.09
kurt	-0.10

==== Sensor: 2_MV_004_STATUS =====

Métrica	Valor
Media	2.00
Desviacion Tipica	0.00
Minimo	2.00
P25	2.00
P75	2.00
Maximo	2.00
varianza	0.00
skew	0.00
kurt	0.00

Métrica	Valor
Media	2.00
Desviacion Tipica	0.00
Minimo	2.00
P25	2.00
P75	2.00
Maximo	2.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_MV_006_STATUS =====

Métrica	Valor
Media	1.16
Desviacion Tipica	0.38
Minimo	0.00
P25	1.00
P75	1.00
Maximo	2.00
varianza	0.15
skew	1.47
kurt	1.45

==== Sensor: 2_MV_009_STATUS =====

Métrica	Valor
Media	2.00
Desviacion Tipica	0.00

Minimo	2.00
P25	2.00
P75	2.00
Maximo	2.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_MV_101_STATUS =====

Métrica	Valor
Media	1.47
Desviacion Tipica	0.50
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.25
skew	0.12
kurt	-1.95

==== Sensor: 2_MV_201_STATUS =====

Métrica	Valor
Media	1.51
Desviacion Tipica	0.50
Minimo	0.00
P25	1.00
P75	2.00

Maximo	2.00
varianza	0.25
skew	-0.06
kurt	-1.96

==== Sensor: 2_MV_301_STATUS =====

Métrica	Valor
Media	1.57
Desviacion Tipica	0.50
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.25
skew	-0.31
kurt	-1.87

==== Sensor: 2_MV_401_STATUS =====

Métrica	Valor
Media	1.42
Desviacion Tipica	0.49
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.24
skew	0.30

kurt	-1.87

==== Sensor: 2_MV_501_STATUS =====

Métrica	Valor
Media	1.50
Desviacion Tipica	0.50
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.25
skew	-0.02
kurt	-1.97

==== Sensor: 2_MV_601_STATUS =====

Métrica	Valor
Media	1.55
Desviacion Tipica	0.50
Minimo	0.00
P25	1.00
P75	2.00
Maximo	2.00
varianza	0.25
skew	-0.19
kurt	-1.93

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_P_002_STATUS =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.00
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_P_003_SPEED =====

Métrica	Valor
Media	3.55
Desviacion Tipica	8.13

Minimo	-0.10
P25	-0.01
P75	-0.01
Maximo	41.62
varianza	66.11
skew	1.95
kurt	2.18

==== Sensor: 2_P_003_STATUS =====

Métrica	Valor
Media	1.17
Desviacion Tipica	0.37
Minimo	1.00
P25	1.00
P75	1.00
Maximo	2.00
varianza	0.14
skew	1.80
kurt	1.26

==== Sensor: 2_P_004_SPEED =====

Métrica	Valor
Media	0.03
Desviacion Tipica	0.01
Minimo	-0.04
P25	0.03
P75	0.04

Maximo	0.04
varianza	0.00
skew	-1.79
kurt	1.79

==== Sensor: 2_P_004_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_PIC_003_CO =====

Métrica	Valor
Media	45.61
Desviacion Tipica	9.57
Minimo	0.00
P25	50.00
P75	50.00
Maximo	50.00
varianza	91.52
skew	-1.92

kurt	2.35
------	------

==== Sensor: 2_PIC_003_PV =====

Métrica	Valor
Media	0.22
Desviacion Tipica	0.42
Minimo	0.01
P25	0.02
P75	0.04
Maximo	3.77
varianza	0.18
skew	2.01
kurt	3.05

==== Sensor: 2_PIC_003_SP =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

Métrica	Valor
Media	152.44
Desviacion Tipica	1.98
Minimo	125.00
P25	151.41
P75	153.83
Maximo	163.33
varianza	3.93
skew	-2.14
kurt	12.10

===== Sensor: 2_PIT_002_PV =====

Métrica	Valor
Media	89.42
Desviacion Tipica	7.13
Minimo	0.00
P25	88.40
P75	92.71
Maximo	98.59
varianza	50.78
skew	-6.60
kurt	65.11

==== Sensor: 2_PIT_003_PV =====

Métrica	Valor
Media	0.22
Desviacion Tipica	0.42

Minimo	0.01
P25	0.02
P75	0.04
Maximo	3.75
varianza	0.18
skew	2.01
kurt	3.04

==== Sensor: 2_SV_101_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_SV_201_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00

Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_SV_301_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_SV_401_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00

Kurt 0.00	kurt	0.00
-----------	------	------

==== Sensor: 2_SV_501_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2_SV_601_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 2A_AIT_001_PV =====

Métrica	Valor
Media	0.17
Desviacion Tipica	0.01
Minimo	0.14
P25	0.16
P75	0.18
Maximo	0.32
varianza	0.00
skew	1.12
kurt	0.86

==== Sensor: 2A_AIT_002_PV =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.05
Minimo	0.00
P25	0.00
P75	0.00
Maximo	7.90
varianza	0.00
skew	81.06
kurt	9737.42

==== Sensor: 2A_AIT_003_PV =====

Métrica	Valor
Media	8.62
Desviacion Tipica	0.11

Minimo	8.19
P25	8.56
P75	8.69
Maximo	8.87
varianza	0.01
skew	-0.46
kurt	-0.05

==== Sensor: 2A_AIT_004_PV =====

Métrica	Valor
Media	483.07
Desviacion Tipica	7.65
Minimo	457.31
P25	478.80
P75	488.23
Maximo	502.00
varianza	58.49
skew	-0.45
kurt	0.47

==== Sensor: 2B_AIT_001_PV =====

Métrica	Valor
Media	0.19
Desviacion Tipica	0.02
Minimo	0.16
P25	0.18
P75	0.20

Maximo	0.23
varianza	0.00
skew	0.96
kurt	0.60

==== Sensor: 2B_AIT_002_PV =====

Métrica	Valor
Media	9.10
Desviacion Tipica	0.13
Minimo	8.52
P25	9.03
P75	9.16
Maximo	23.90
varianza	0.02
skew	23.74
kurt	2500.28

==== Sensor: 2B_AIT_003_PV =====

Métrica	Valor
Media	8.58
Desviacion Tipica	0.12
Minimo	6.73
P25	8.52
P75	8.67
Maximo	8.87
varianza	0.02
skew	-0.98

kurt	6.42
------	------

==== Sensor: 2B_AIT_004_PV =====

Métrica	Valor
Media	487.37
Desviacion Tipica	8.39
Minimo	0.00
P25	483.13
P75	492.42
Maximo	571.27
varianza	70.33
skew	-3.56
kurt	189.31

==== Sensor: 3_AIT_001_PV =====

Métrica	Valor
Media	0.00
Desviacion Tipica	0.02
Minimo	0.00
P25	0.00
P75	0.00
Maximo	0.16
varianza	0.00
skew	7.31
kurt	51.39

Métrica	Valor
Media	7170.69
Desviacion Tipica	2725.96
Minimo	0.00
P25	8279.10
P75	8279.10
Maximo	8287.53
varianza	7430831.07
skew	-2.21
kurt	2.98

===== Sensor: 3_AIT_003_PV =====

Métrica	Valor
Media	8.72
Desviacion Tipica	7.82
Minimo	0.00
P25	3.14
P75	11.95
Maximo	40.43
varianza	61.13
skew	1.16
kurt	0.89

==== Sensor: 3_AIT_004_PV =====

Métrica	Valor
Media	628.61
Desviacion Tipica	535.00

Minimo	-1285.99
P25	406.66
P75	933.83
Maximo	2414.33
varianza	286229.79
skew	-0.52
kurt	0.47

==== Sensor: 3_AIT_005_PV =====

Métrica	Valor
Media	0.68
Desviacion Tipica	0.16
Minimo	0.07
P25	0.62
P75	0.78
Maximo	1.21
varianza	0.03
skew	-1.20
kurt	0.46

==== Sensor: 3_FIT_001_PV =====

Métrica	Valor
Media	0.53
Desviacion Tipica	0.26
Minimo	0.00
P25	0.56
P75	0.68

Maximo	1.16
varianza	0.07
skew	-1.36
kurt	0.17

===== Sensor: 3_LS_001_AL =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 3_LT_001_PV =====

Métrica	Valor
Media	65.14
Desviacion Tipica	1.16
Minimo	63.97
P25	64.30
P75	65.92
Maximo	69.17
varianza	1.35
skew	1.25

kurt	0.45
------	------

==== Sensor: 3_MV_001_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 3_MV_002_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 3_P_001_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 3_P_002_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00

Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 3_P_003_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: 3_P_004_STATUS =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00

Maximo	1.00
varianza	0.00
skew	0.00
kurt	0.00

==== Sensor: LEAK_DIFF_PRESSURE =====

Métrica	Valor
Media	63.01
Desviacion Tipica	5.72
Minimo	48.67
P25	60.48
P75	63.65
Maximo	144.19
varianza	32.74
skew	7.39
kurt	76.93

==== Sensor: PLANT_START_STOP_LOG =====

Métrica	Valor
Media	1.00
Desviacion Tipica	0.00
Minimo	1.00
P25	1.00
P75	1.00
Maximo	1.00
varianza	0.00
skew	0.00

==== Sensor: TOTAL_CONS_REQUIRED_FLOW =====

Métrica	Valor
Media	0.55
Desviacion Tipica	0.45
Minimo	0.00
P25	0.22
P75	0.73
Maximo	2.26
varianza	0.20
skew	1.01
kurt	1.21