


 Quality
 Generated : 04:53:10 13 May 2025

 Leadership
 CRAIOVA Plant
 Printed : 05:13:39 13 May 2025

 System
 *V769 LICENSE LAMP LOOSE
 By : RAZVAN CIRJU



	С	Υ		Week Starting							Day									
Actual Unit Concern /1000	0.677	0.267	0.286	0.139	0.347	0.109	0.457 0.	.42	0.484	0	0	1.806	0.499	0	0	0	2.557	0	0	0
Sample Size	82693	33656	6991	7153	8643	9113	6551 23	376	2064	2091	1738	1107	2002	341	371	390	391	393	115	310
Actual Unit Concern /1000	0.677	0.267	0.286	0.139	0.347	0.109	0.457 0.	.42	0.484	0	0	1.806	0.499	0	0	0	2.557	0	0	0
FTT Not-OK Units Count	52	9	2	1	3	1	3	1	1	0	0	2	1	0	0	0	1	0	0	0
First Run %	99.93	99.97	99.97	99.99	99.97	99.99	99.95 99	.96	99.95	100	100	99.82	99.95	100	100	100	99.74	100	100	100
Actual Unit Concern Count	56	9	2	1	3	1	3	1	1	0	0	2	1	0	0	0	1	0	0	0
Undefined Unit Concern /1000	0	0.029	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

	Actual Unit Concern,/1000																				
	C	Υ	Month						Week Starting							Day					
									30	6	13	27	4	11	6	7	8	9	10	12	
	2024	2025	Dec	Jan	Feb	Mar	Apr	May	Mar	Apr	Apr	Apr	May	May	May	May	May	May	May	May	
LicenseLamp NOT SEATED	0.133	0.178	0.286	0.139	0	0.109	0.457	0.42	0.484	0	0	1.806	0.499	0	0	0	2.557	0	0	0	
LIFT GATE	0.048	0.059	0	0.139	0	0	0	0.42	0	0	0	0	0.499	0	0	0	2.557	0	0	0	
LicenseLamp POOR APPEARANCE	0.193	0.059	0	0	0.231	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LIFT GATE	0.024	0.029	0	0	0.115	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
CARGO DOOR	0.133	0.029	0	0	0.115	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LicenseLamp LOOSE	0.278	0.029	0	0	0.115	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LEFT	0	0.029	0	0	0.115	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LicenseLamp IMPROPER ASSEMBLY	0.048	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
CARGO DOOR	0.036	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LEFT REAR DOOR	0.012	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LicenseLamp MISSING	0.024	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
LIFT GATE	0.012	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
CARGO DOOR	0.012	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
																	Pareto Po	pulation	Percent	0%	