


Quality Leadership System

BX726 GEAR SHIFT

CRAIOVA Plant
*BX726 GEAR SHIFT

Generated: 04:19:53 09 May 2025
Printed: 04:54:16 09 May 2025

A Plant Generated: 04:19:53 09 May 2025
A Plant Printed: 04:54:16 09 May 2025
AR SHIFT By: GABRIEL CIRLOGEA



		CY	Month						Week Starting							Day						
Actual Unit Concern /1000	0.7	0.368	0.587	0.301	0.093	0.28	0.631	1.074	0.285	0.855	0.535	0.362	1.133	0.728	0	1.697	3.11	0	0	0		
Sample Size	165545	48789	13621	9955	10749	14285	11078	2792	3498	3508	3732	2761	1764	2746	618	589	643	655	776	663		
Actual Unit Concern /1000	0.7	0.368	0.587	0.301	0.093	0.28	0.631	1.074	0.285	0.855	0.535	0.362	1.133	0.728	0	1.697	3.11	0	0	0		
FTT Not-OK Units Count	112	18	8	3	1	4	7	3	1	3	2	1	2	2	0	1	2	0	0	0		
First Run %	99.93	99.96	99.94	99.97	99.99	99.97	99.94	99.89	99.97	99.91	99.95	99.96	99.89	99.93	100	99.83	99.69	100	100	100		
Actual Unit Concern Count	116	18	8	3	1	4	7	3	1	3	2	1	2	2	0	1	2	0	0	0		
Undefined Unit Concern /1000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		

	Actual Unit Concern,/1000																				
	C	Y	Month						Week Starting							Day					
									23	30	6	13	27	4	29	- 1	30	5 6		7	8
	2024	2025	Dec	Jan	Feb	Mar	Apr	May	Mar	Mar	Apr	Apr	Apr	May	Apr	. :	Apr	Ma	y Ma	/ May	May
GearShift IMPROPER FUNCTION	0.465	0.184	0.44	0.2	0.093	0.07	0.18	1.074	0	0.285	0	0.362	0.566	0.728	0		0	3.1	1 0	0	0
GearShift IMPROPER ADJUST	0.199	0.184	0.146	0.1	0	0.21	0.451	0	0.285	0.57	0.535	0	0.566	0	0		1.697	0	0	0	0
GearShift DRAG	0.018	0	0	0	0	0	0	0	0	0	0	0	0	0	0	- :	0	0	0	0	0
GearShift INOPERATIVE	0.006	0	0	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0	0
GearShift LOCKED	0.006	0	0	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0	0
GearShift STICKING	0.006	0	0	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0	0

Pareto Population Percent 0%