Conductivity Calibration Report

Customer:	Pacific Marine E	nvironmental Lab				
Job Number:	86981		Date of Report:		11/23/2015	
Model Number	SBE 37SM		Serial Numb	er:	37SM360	48-3768
sensor drift. If the	calibration identifies a rk is completed. The 'd	ted 'as received', withou problem or indicates co as received' calibration i	ell cleaning is nec	essary, then	a second co	alibration is
conductivity. Users sensor condition du corrections for drift	must choose whether t cring deployment. In S	rovided, listing the coefy he 'as received' calibra SEASOFT enter the cho consult the SEASOFT in t data.	tion or the previou sen coefficients.	us calibratio The coeffici	on better rep ent 'slope' a	presents the llows small
'AS RECEIVED C	CALIBRATION'		✓ Per	formed	☐ Not	Performed
Date: 11/22/2015	5	Drift si	nce last cal:	-0.0	0110	PSU/month
Comments:						
'CALIBRATION	AFTER CLEANING	G & REPLATINIZIN	[G' ☐ Per	formed	✓ Not	Performed
Date:		Drift si	nce Last cal:			PSU/month
Comments:						
*Measured at 3.0	S/m					

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.