PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

## **ECO CDOM Fluorometer Characterization Sheet**

Date: 5/15/2015 S/N: BBFL2WB-1307

CDOM concentration expressed in ppb can be derived using the equation:

CDOM (ppb) = Scale Factor \* (Output - Dark Counts)

Dark Counts

Scale Factor (SF)

Maximum Output

Resolution

Digital

48 counts

0.0908 ppb/count

4130 counts

1.1 counts

Ambient temperature during characterization 22.3 °C

**Dark Counts:** Signal output of the meter in clean water with black tape over detector.

**SF:** Determined using the following equation:  $SF = x \div (output - dark counts)$ , where x is the concentration of the solution used during instrument characterization. SF is used to derive instrument output concentration from the raw signal output of the fluorometer.

Maximum Output: Maximum signal output the fluorometer is capable of.

Resolution: Standard deviation of 1 minute of collected data.

BBFL2WB-1307.xls Revision S 10/4/07