Conductivity Calibration Report

Customer:	Pacific Marine E	nvironmental Lab			
Job Number:	83020	Date of Repo	ort:	2/6/2	2015
Model Number	SBE 16-03	Serial Numb	er:	164208	8-0653
sensor drift. If the	calibration identifies a rk is completed. The 'd	ted 'as received', without cleaning or adju problem or indicates cell cleaning is ned as received' calibration is not performed i	essary, then	a second c	alibration is
conductivity. Users sensor condition du corrections for drift repair or cleaning d	must choose whether turing deployment. In state to the state of the st		us calibration The coefficition coeffici	on better re ent 'slope' d ients obtain	presents the allows small ed after a
'AS RECEIVED O	CALIBRATION'	✓ Per	formed		t Performed
Date: 1/23/2015		Drift since last cal:	-0.0	0160	PSU/month*
Comments:					
'CALIBRATION	AFTER REPAIR'	✓ Per	formed	□ No	t Performed
Date: 2/6/2015		Drift since Last Cal:	N	I/A	PSU/month*
Comments: The conductivity of	cell was replaced.				

*Measured at 3.0 S/m

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.