Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 5584 CALIBRATION DATE: 02-Feb-16 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.32870738e-003 h = 6.29036199e-004 i = 1.90813696e-005 j = 1.25458942e-006 f0 = 1000.0

BATH TEMP (° C)	INSTRUMENT OUTPUT (Hz)	INST TEMP (° C)	RESIDUAL (° C)
-1.5000	2889.618	-1.5000	-0.00005
1.0000	3058.237	1.0001	0.00006
4.5000	3306.141	4.5000	0.00001
7.9999	3568.246	7.9999	0.00003
11.5000	3844.979	11.5000	-0.00001
15.0000	4136.725	15.0000	-0.00003
18.5000	4443.884	18.4999	-0.00009
22.0000	4766.859	22.0000	-0.00001
25.5000	5106.020	25.5001	0.00011
29.0000	5461.714	29.0001	0.00006
32.5000	5834.306	32.4999	-0.00007

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

