## **SEA-BIRD ELECTRONICS, INC.**

13431 NE 20th Street, Bellevue, Washington, 98005-2010 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 1851 CALIBRATION DATE: 19-Jan-11 SBE 37 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = -2.984324e-005 a1 = 2.833622e-004 a2 = -2.895140e-006a3 = 1.713239e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	634064.4	1.0000	-0.0000
4.5000	543156.0	4.5000	0.0000
15.0000	348015.1	15.0001	0.0001
18.5000	301853.5	18.4998	-0.0002
23.9999	242769.2	24.0000	0.0001
29.0000	200343.5	29.0000	-0.0000
32.4999	175708.3	32.4999	-0.0000

Temperature ITS-90 =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)



