Conductivity Calibration Report

Customer:	Pacific Marine E	nvironmental Lab				
Job Number:	86981	Date of Repo	rt:	12/1/2015		
Model Number	SBE 16Plus		Serial Numb	er:	16P29504-4285	
sensor drift. If the	calibration identifies a rk is completed. The 'd	ted 'as received', withou problem or indicates co as received' calibration i	ell cleaning is nec	essary, then	a second co	alibration is
conductivity. Users sensor condition du corrections for drift	must choose whether t ring deployment. In S	provided, listing the coeff the 'as received' calibrat SEASOFT enter the cho (consult the SEASOFT in the data.	ion or the previou sen coefficients. Z	is calibration The coeffici	on better rep ient 'slope' d	presents the allows small
'AS RECEIVED C	CALIBRATION'		✓ Per	formed	□ No	t Performed
Date: 11/26/2015	5	Drift si	nce last cal:	-0.0	0020	PSU/month
Comments:						
'CALIBRATION	AFTER CLEANING	G & REPLATINIZIN	G' Peri	formed	✓ Not	t Performed
Date:		Drift si	nce Last cal:			PSU/month
Comments:						
*Measured at 3.0	S/m					

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.