Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

## SENSOR SERIAL NUMBER: 5895 CALIBRATION DATE: 26-Feb-19

## SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

g = 4.32208493e-003 h = 6.37262480e-004 i = 2.24862941e-005 j = 2.13717785e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	2829.413	-1.5000	-0.00002
1.0000	2993.201	1.0000	0.00002
4.5000	3233.907	4.5000	0.00004
8.0000	3488.260	8.0000	-0.00001
11.5000	3756.643	11.5000	-0.00001
15.0000	4039.412	14.9999	-0.00008
18.5000	4336.941	18.5000	0.00003
22.0000	4649.555	22.0001	0.00009
25.5000	4977.573	25.5000	-0.00000
29.0000	5321.330	28.9999	-0.00008
32.5000	5681.148	32.5000	0.00003

f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0 / f)] + i[ln^2(f0 / f)] + j[ln^3(f0 / f)]\} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

