Customer:

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Pacific Marine Environmental Lab

86981	Date of Rep	oort:	11/23/2015
SBE 37SM	Serial Num	ber:	37SM26834-2022
ntifies a problem, then erformed if the sensor libration certificate is p	a second calibration is performed after vis damaged or non-functional, or by cus rovided, listing coefficients to convert so	work is complet stomer request. ensor frequenc	ted. The 'as received' v to temperature. Users
. In SEASOFT enter t	he chosen coefficients. The coefficient	'offset' allows	a small correction for
CALIBRATION'	☑ Pe	erformed	☐ Not Performed
CALIBRATION'	✓ Performance	erformed +0.00031	
	Drift since last cal:		Degrees Celsius/year Not Performed
5	Drift since last cal:	+0.00031	Degrees Celsius/year
	SBE 37SM rs are normally calibra ntifies a problem, then a erformed if the sensor a libration certificate is p er the 'as received' cali . In SEASOFT enter the	SBE 37SM Serial Num The state of Tell Serial Num The state of T	Butt of Report