## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0511 CALIBRATION DATE: 06-Oct-16

SBE 39 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

a0 = -2.867034e-005 a1 = 2.819496e-004 a2 = -2.781418e-006 a3 = 1.709934e-007

BATH TEMP (° C)	INSTRUMENT OUTPUT (counts)	INST TEMP (° C)	RESIDUAL (° C)
-1.5000	704964.2	-1.5000	0.0000
1.0000	630240.3	1.0000	-0.0000
4.5000	540271.3	4.5000	-0.0000
8.0001	464636.6	8.0001	-0.0000
11.5000	400844.5	11.5000	0.0000
15.0000	346863.2	15.0000	0.0000
18.5000	301039.8	18.5000	0.0000
22.0000	262021.5	22.0000	-0.0000
25.5000	228698.1	25.4999	-0.0001
29.0000	200155.0	28.9999	-0.0001
32.5000	175636.7	32.5001	0.0001

n = Instrument Output (counts)

Temperature ITS-90 (°C) =  $1/\{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]\}$  - 273.15

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

