

SEA-BIRD ELECTRONICS, INC.

13431 NE 20th Street Bellevue, Washington 98005 USA Phone +1-425-643-9866 Fax +1-425-643-9954 www.seabird.com

SERVICE REPORT Service Request 1005501689
Date 13-APR-2017

CUSTOMER INFORMATION

Name: NOAA PMEL - PACIFIC MARINE ENVIRO LAB

Account: 40279844 DAVID STRAUSZ

DAVID.STRAUSZ@NOAA.GOV

206-526-4510

Bill To Address

7600 SAND POINT WAY NE;

SEATTLE,WA,98115-6349,US

Ship To Address

SUPPLY CENTER / RECEIVING;7600 SAND POINT WAY NE,

PO Number:

BLDG 8;

SEATTLE,WA,98115,US

PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

Serial: 16P31373-4424

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.
Replace the instruments "O"-rings.
Perform hydrostatic pressure test.
Replace Antifoulant Device(s).

Problems Found:

The lithium backup batteries had reached the end of their life expectancy.

Services Performed:

Performed initial diagnostic evaluation.

Performed "POST" cruise calibration.

Replaced the lithium back-up battery(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed complete system check and full diagnostic evaluation.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	CONFIRM / RECERTIFY SBE 16/16PLUS/16PLUSV2. COMPLETE	1
	EXTERNAL INSPECTION. TEST ALL FUNCTIONS AND INPUT	
	CHANNEL RESPONSES (FRRF)	
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES	2
	ONE 801542.1. (FRRF)	

			14	
Un	ומו	nea	Items	



SEA-BIRD ELECTRONICS, INC. 13431 NE 20th Street Bellevue, Washington 98005 USA

Phone +1-425-643-9866 Fax +1-425-643-9954 www.seabird.com

SERVICE REPORT Service Request 1005501689 **Date** 13-APR-2017

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22009	LITHIUM BATTERY, PANASONIC BR 2/3 A-T2SP	3



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th Street Bellevue, Washington 98005 USA Phone +1-425-643-9866 Fax +1-425-643-9954 www.seabird.com

SERVICE REPORT **Service Request**

1005501689 **Date** 13-APR-2017

PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

Serial: 16P31373-4425

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service. Replace the instruments "O"-rings. Perform hydrostatic pressure test. Replace Antifoulant Device(s).

Problems Found:

The lithium backup batteries had reached the end of their life expectancy.

Services Performed:

Performed initial diagnostic evaluation.

Performed "POST" cruise calibration. Replaced the lithium back-up battery(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed complete system check and full diagnostic evaluation.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	CONFIRM / RECERTIFY SBE 16/16PLUS/16PLUSV2. COMPLETE	1
	EXTERNAL INSPECTION. TEST ALL FUNCTIONS AND INPUT	
	CHANNEL RESPONSES (FRRF)	
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE 801542.1. (FRRF)	2

Unbilled Items

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22009	LITHIUM BATTERY, PANASONIC BR 2/3 A-T2SP	3



SERVICE REPORT

SEA-BIRD ELECTRONICS, INC.

13431 NE 20th Street Bellevue, Washington 98005 USA Phone +1-425-643-9866 Fax +1-425-643-9954 www.seabird.com

Service Request Date

1005501689 13-APR-2017

PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

Serial: 16P31373-4426

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service. Replace the instruments "O"-rings. Perform hydrostatic pressure test. Replace Antifoulant Device(s).

Problems Found:

The lithium backup batteries had reached the end of their life expectancy.

Services Performed:

Performed initial diagnostic evaluation.

Performed "POST" cruise calibration. Replaced the lithium back-up battery(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed complete system check and full diagnostic evaluation.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	CONFIRM / RECERTIFY SBE 16/16PLUS/16PLUSV2. COMPLETE	1
	EXTERNAL INSPECTION. TEST ALL FUNCTIONS AND INPUT CHANNEL RESPONSES (FRRF)	
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE 801542.1. (FRRF)	2

Unbilled Items

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	1
22009	LITHIUM BATTERY, PANASONIC BR 2/3 A-T2SP	3