## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 6592 CALIBRATION DATE: 07-Feb-14

SBE16plusV2 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 1.282045e-003a1 = 2.585935e-004a2 = -6.545927e - 008a3 = 1.416722e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT(n)	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	648521.400	1.0000	0.0000
4.5000	575676.400	4.4999	-0.0001
15.0000	394410.200	15.0001	0.0001
18.5000	345705.364	18.5000	-0.0000
24.0000	279626.700	23.9999	-0.0001
29.0000	229401.500	29.0000	0.0000
32.5000	199115.600	32.5000	0.0000

MV = (n - 524288) / 1.6e + 007

R = (MV \* 2.900e+009 + 1.024e+008) / (2.048e+004 - MV \* 2.0e+005)

Temperature ITS-90 =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

