Conductivity Calibration Report

Customer:	Pacific Marine En	vironmental Lab		
Job Number:	86981	Date of R	eport:	11/20/2015
Model Number	SBE 37SM	Serial Nu	mber:	37SM25541-1858
sensor drift. If the	calibration identifies a rk is completed. The 'as	ed 'as received', without cleaning or a problem or indicates cell cleaning is s received' calibration is not perform	necessary, the	en a second calibration is
conductivity. Users sensor condition du corrections for drift	must choose whether the ring deployment. In S.	rovided, listing the coefficients used to be 'as received' calibration or the pre EASOFT enter the chosen coefficien consult the SEASOFT manual). Cali t data.	vious calibrati ts. The coeffic	ion better represents the cient 'slope' allows small
'AS RECEIVED (CALIBRATION'	✓]	Performed	☐ Not Performed
Date: 11/20/2015	5	Drift since last cal:	+0.	00010 PSU/mont
Comments:				
'CALIBRATION	AFTER CLEANING	& REPLATINIZING'	Performed	✓ Not Performed
Date:		Drift since Last cal	:	PSU/mont
Comments:				
*Measured at 3.0	S/m			

Cell cleaning and electrode replatinizing tend to 'reset' the conductivity sensor to its original condition. Lack of drift in post-cleaning-calibration indicates geometric stability of the cell and electrical stability of the sensor circuit.