Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 7021 CALIBRATION DATE: 21-Dec-17

SBE 16plus V2 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

a0 = 1.238664e-003 a1 = 2.794728e-004 a2 = -1.737176e-006 a3 = 2.061146e-007

| BATH TEMP | INSTRUMENT | INST TEMP | RESIDUAL |
|-----------|-----------------|-----------|----------|
| (° C) | OUTPUT (counts) | (° C) | (° C) |
| 1.0000 | 564052.400 | 1.0000 | 0.0000 |
| 4.5000 | 498083.000 | 4.4999 | -0.0001 |
| 15.0000 | 336785.100 | 15.0001 | 0.0001 |
| 18.5000 | 294077.900 | 18.4999 | -0.0001 |
| 23.9999 | 236506.900 | 23.9999 | -0.0000 |
| 29.0000 | 193004.500 | 29.0000 | 0.0000 |
| 32.5000 | 166866.000 | 32.5000 | -0.0000 |

n = Instrument Output (counts)

MV = (n - 524288) / 1.6e + 007

R = (MV * 2.900e + 0.09 + 1.024e + 0.08) / (2.048e + 0.04 - MV * 2.0e + 0.05)

Temperature ITS-90 (°C) = $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

