Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 2786 CALIBRATION DATE: 03-Jun-23 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.37636659e-003 h = 6.44251494e-004 i = 2.28752541e-005 j = 2.11988740e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3061.362	-1.4999	0.00007
1.0000	3237.470	0.9999	-0.00005
4.5000	3496.174	4.4999	-0.00009
8.0000	3769.415	8.0000	-0.00003
11.5000	4057.582	11.5001	0.00010
15.0000	4361.038	15.0001	0.00012
18.5000	4680.144	18.5000	-0.00003
22.0000	5015.276	21.9999	-0.00010
25.5000	5366.786	25.5000	-0.00001
29.0000	5734.980	29.0000	-0.00000
32.5000	6120.183	32.5000	0.00003

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0 / f)] + i[ln^2(f0 / f)] + j[ln^3(f0 / f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

