## SAT-QR-99016 (v 1.1.0)**Verification Checklist PAR** Serial Number: 1086 TDP: 2.1.0 Firmware: 2.3.0 Project Number: 2016-7069 Model: Shallow (PAR 1000m) TV AUV (PAR-AUV 1000m) Deep (PAR 7000m) Serial -Options: Log I Linear I In-Air In-Water IV Accessories: RS-232 Cable RS-232 and Analog Cable Shallow Deep AUV USB Cable Calibration Saturation: 75/80 µmol photons•m<sup>-2</sup>•s<sup>-1</sup> Date: 10 11 12616 Pressure test not required Pressure Test Rated to: Active current (at 12 Vdc) $\underline{jq_m H}$ ( $\leq$ 25 mA) No pin-to-pin shorts $\overline{V}$ Ground fault free $\overline{V}$ Performance Agreement: 3.03% (< 5%) Reality Check Date: 10 111 12016 Calibration coefficients stored (Serial only) N/A Configuration Analog Out: OK N/A Standard settings configuration IV N/A I Custom configuration | N/A | Cables: OK N/A Accessories Check Optical surfaces clean Finishing SIP file tested with SatView N/A

This final inspection and verification of the PAR sensor is performed after all other work is complete. The inspection is conducted and QA countersigned by qualified Satlantic technicians.

**Quality Assurance:** 



Date:

2016 / 11 / 10