## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 4287 CALIBRATION DATE: 10-Jul-12

SBE16plus TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 1.266876e - 003a1 = 2.579820e - 004a2 = 5.323612e-007a3 = 1.269574e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT(n)	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	623727.800	1.0000	0.0000
4.5000	553888.000	4.4999	-0.0001
15.0000	380504.200	15.0000	-0.0000
18.5000	333940.800	18.5002	0.0002
24.0000	270733.800	23.9999	-0.0001
29.0000	222619.364	29.0000	-0.0000
32.5000	193559.909	32.5000	0.0000

MV = (n - 524288) / 1.6e + 007

R = (MV \* 2.900e+009 + 1.024e+008) / (2.048e+004 - MV \* 2.0e+005)

Temperature ITS-90 =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

