SEA-BIRD ELECTRONICS, INC.

13431 NE 20th Street, Bellevue, Washington, 98005-2010 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 1869 CALIBRATION DATE: 11-Jan-11 SBE 37 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS

a0 = -1.955932e-005 a1 = 2.804876e-004 a2 = -2.636418e-006 a3 = 1.672272e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	616753.1	1.0000	0.0000
4.5000	528772.3	4.4999	-0.0001
15.0000	339598.7	15.0000	0.0000
18.5000	294768.8	18.5001	0.0001
24.0000	237340.3	23.9999	-0.0001
29.0000	196053.4	28.9999	-0.0001
32.5000	172057.1	32.5000	0.0000

Temperature ITS-90 = $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$ (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)



