Sea-Bird Scientific 13431 NE 20<sup>th</sup> Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 7021 SBE 16plus V2 TEMPERATURE CALIBRATION DATA CALIBRATION DATE: 14-Jan-21 ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

a0 = 1.259775e-003 a1 = 2.716381e-004 a2 = -7.689717e-007 a3 = 1.662311e-007

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (counts)	(° C)	(° C)
0.9999	564095.100	0.9999	0.0000
4.5000	498115.200	4.5000	-0.0000
15.0000	336809.500	15.0000	0.0000
18.5000	294098.500	18.4999	-0.0001
24.0000	236519.100	24.0002	0.0002
29.0000	193014.800	28.9997	-0.0003
32.5000	166867.300	32.5001	0.0001

n = Instrument Output (counts)

MV = (n - 524288) / 1.6e + 007

R = (MV \* 2.900e+009 + 1.024e+008) / (2.048e+004 - MV \* 2.0e+005)

Temperature ITS-90 (°C) =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$ 

Residual ( $^{\circ}$ C) = instrument temperature - bath temperature

