

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

> **Service Request Date**

> > PO Number:

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com 1005507497

07-MAY-2019

Sales Order

CUSTOMER INFORMATION

Name: NOAA Account: 40299841 **David Strausz**

david.strausz@noaa.gov

1-206-526-4510

Bill To Address 7600 SAND POINT WAY NE; SEATTLE, WA, 98115, US

Ship To Address 7600 SAND POINT WAY NE: SEATTLE,WA,98115,US

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM40084-3979

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

> Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497** 07-MAY-2019

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1851

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

> Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497** 07-MAY-2019

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2321

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

> **Service Request Date**

+1-425-643-9866 +1-425-643-9954 www.seabird.com 1005507497

07-MAY-2019

Sales Order

Phone

Fax

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1850

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497**

Service Request
Date
Sales Order

07-MAY-2019

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM29475-2357

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

> **Service Request Date**

+1-425-643-9866 +1-425-643-9954 www.seabird.com 1005507497

07-MAY-2019

SERVICE REPORT

Sales Order

Phone

Fax

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1860

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

> **Service Request Date**

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com 1005507497 07-MAY-2019

SERVICE REPORT

Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1852

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

Service Request Date

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com 1005507497

07-MAY-2019

Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2328

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497** 07-MAY-2019

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM36048-3767

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Gilbillou itolilo		
Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

> Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497**

07-MAY-2019

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2332

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

> **Service Request Date**

+1-425-643-9866 +1-425-643-9954 www.seabird.com 1005507497

07-MAY-2019

Sales Order

Phone

Fax

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM36048-3764

Special Notes

Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497** 07-MAY-2019

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25429-1807

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

Service Request Date Sales Order

Phone

Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com **1005507497** 07-MAY-2019

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37-2318

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Replace antifoulant device(s).

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2