+1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 3114 CALIBRATION DATE: 05-May-19 SBE 16 CONDUCTIVITY CALIBRATION DATA PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

i = -3.67859278e-005

BATH TEMP	BATH SAL	BATH COND	INSTRUMENT		RESIDUAL
(° C)	(PSU)	(S/m)	OUTPUT (kHz)	COND (S/m)	(S/m)
22.0000	0.0000	0.0000	2.88534	0.0000	0.00000
1.0000	34.7657	2.97205	8.22494	2.97202	-0.00003
4.5000	34.7457	3.27872	8.58678	3.27875	0.00003
15.0000	34.7032	4.25920	9.65144	4.25925	0.00005
18.5000	34.6940	4.60389	9.99832	4.60388	-0.00001
23.9999	34.6832	5.16100	10.53451	5.16094	-0.00006
29.0000	34.6745	5.68170	11.01182	5.68172	0.00002
32.5000	34.6675	6.05297	11.33965	6.05298	0.00001

f = Instrument Output (kHz)

 $t = temperature \; (^{\circ}C); \quad p = pressure \; (decibars); \quad \delta = CTcor; \quad \epsilon = CPcor;$

Conductivity (S/m) = (g + h * f^2 + i * f^3 + j * f^4) /10 (1 + δ * t + ϵ * p)

Residual (Siemens/meter) = instrument conductivity - bath conductivity

