Pacific Marine Environmental Lab

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Temperature Calibration Report

Customer:	Pacific Marine Env	ironmental Lab		
Job Number:	86981	Date of Rep	ort:	12/1/2015
Model Number	SBE 39	Serial Numl	99	39602-1807
the calibration iden calibration is not p	ntifies a problem, then a se erformed if the sensor is d	l 'as received', without adjustments, a econd calibration is performed after w lamaged or non-functional, or by cust vided, listing coefficients to convert se	ork is completed. omer request.	The 'as received'
must choose wheth during deployment	er the 'as received' calibra . In SEASOFT enter the rations (consult the SEAS	ution or the previous calibration bette chosen coefficients. The coefficient ' OFT manual). Calibration coefficien	r represents the sec offset' allows a sm	nsor condition all correction for
Date: 12/1/2015	<u> </u>	Drift since last cal:	+0.00010	Degrees Celsius/year
Comments:	_	·		
'CALIBRATION	AFTER REPAIR'	□ Pe	formed 🗸	Not Performed
Date:]	Drift since Last cal:		Degrees Celsius/year
Comments:				