SEA-BIRD ELECTRONICS, INC.

13431 NE 20th Street, Bellevue, Washington, 98005-2010 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 6629 CALIBRATION DATE: 10-Jun-11

SBE16plus TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS

a0 = 1.235093e-003a1 = 2.540243e-004a2 = 4.581042e-007a3 = 1.170086e - 007

| BATH TEMP (ITS-90) | INSTRUMENT OUTPUT(n) | INST TEMP (ITS-90) | RESIDUAL (ITS-90) |
|-----------------------|-------------------------|-----------------------|----------------------|
| 0.9999 | 756064.900 | 1.0000 | 0.0001 |
| 4.4999 | 677374.600 | 4.4998 | -0.0001 |
| 14.9999 | 476257.500 | 15.0000 | 0.0001 |
| 18.5000 | 420876.909 | 18.5001 | 0.0001 |
| 24.0000 | 344803.400 | 23.9998 | -0.0002 |
| 28.9999 | 286230.455 | 29.0000 | 0.0001 |
| 32.5000 | 250593.364 | 32.5000 | -0.0000 |

MV = (n - 524288) / 1.6e + 007

R = (MV * 2.900e+009 + 1.024e+008) / (2.048e+004 - MV * 2.0e+005)

Temperature ITS-90 = $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$ (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

0.00

