## Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0042 CALIBRATION DATE: 03-May-13

SBE 49 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = 6.973450e-004 a1 = 3.239442e-004 a2 = -6.262367e-006 a3 = 3.507807e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT(n)	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	698810.678	1.0000	-0.0000
4.5000	617648.000	4.5000	0.0000
15.0000	412655.339	15.0000	0.0000
18.5000	356660.153	18.5001	0.0001
24.0000	279926.186	23.9996	-0.0004
29.0061	220829.898	29.0067	0.0006
32.5119	184868.458	32.5116	-0.0003

MV = (n - 524288) / 1.6e + 007


R = (MV \* 2.295e+010 + 9.216e+008) / (6.144e+004 - MV \* 5.3e+005)

Temperature ITS-90 =  $1/{a0 + a1[ln(R)] + a2[ln^2(R)] + a3[ln^3(R)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)

● 03-May-13 -0.00



CALIBRATION
AFTER
MODIFICATIONS