The temperature probe was replaced.

Temperature Calibration Report

Customer:	Pacific Marine Environmental Lab		
Job Number:	65422	Date of Repo	ort: 9/13/2011
Model Number	SBE 39	Serial Numb	er: 3939602-1777
If the calibration id calibration is not po An 'as received' cal must choose wheth during deployment, allows a small corre	lentifies a problem, then erformed if the sensor is libration certificate is payed the 'as received' calificate the 'As Technology of the the ction for drift between the air apply only to subsection.	•	work is completed. The 'as received' omer request. sor frequency to temperature. Users represents the sensor condition SEACON. The coefficient 'offset'
Date: 8/18/2011		Drift since last cal:	+0.00009 Degrees Celsius/year
Comments:			
The temperature	probe was found to	be bent.	
'CALIBRATION	AFTER REPAIR'	✓ Per	formed
Date: 9/13/2011		Drift since Last cal:	N/A Degrees Celsius/year
Comments:			