PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

Chlorophyll WETStar Characterization

Date: January 17, 2017 S/N: WS3S-732P

Chlorophyll concentration expressed in µg/l can be derived using the equation:

 $CHL(\mu g/I) = Scale Factor x (Output - Clean Water Offset)$

Analog output

Clean Water Offset (CWO) 0.080 V
Scale Factor (SF) 6.7 μg/l/V

Maximum Output 5.53 V Resolution 0.48 mV Ambient Characterization Temperature 22 \pm 1°C

Current Draw 30 mA @ 12V (typical)

12-hour Stability 0.32 mV/hr Temperature Stability, 25–2 °C 0.23 mV/°C

Range	
15 μg/l	0
75 μg/l	Χ
150 µg/l	0

Definitions:

CWO: Clean Water Offset value obtained using pure filtered de-ionized water.

SF: Scale Factor is used to convert the fluorescence response of the instrument into chlorophyll-a concentration. Scale Factor is determined at WET Labs during a cross calibration using a liquid fluorescent standard and a reference fluorometer whose chlorophyll fluorescence response has been characterized in a laboratory using a mono-species lab culture of *Thalassiosira weissflogii* phytoplankton.

Maximum Output: Maximum signal output of the fluorometer.

Resolution: Standard deviation of 1 minute of clean water data, sampled once per second.

Ambient Characterization Temperature: Room temperature at time of characterization.

Current Draw: The amount of current the instrument uses for operation.

12-hour Stability: Deviation of output averaged over 12 hours.

Temperature Stability: Measured output variation per degree.

PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

WETStar Calibration and Repairs

Date January 17, 2017 Customer NOAA

S/N# WS3S-732P Repair Order 32800

Standard Service

- Performed noise test: 1 sample/sec for 60 sec
- Performed stability test: 1 sample/min for 12 hrs
- Performed temperature test: 25-2 °C
- · Performed saturation test
- Shake-tested unit
- Pressure-tested unit
- Updated unit's calibration sheet

Diagnosis

Evaluated Instrument and found no problems. Standard Service.

Repairs

Replaced the O-Rings.

Comments