

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866 Fax +1-425-643-9954

www.seabird.com

Service Request Date Sales Order

PO Number:

1005507587 17-MAY-2019

315570150

SERVICE REPORT

CUSTOMER INFORMATION

Name: NOAA/ALASKA FISHERIES SCIENCE CENTER

Account: 40280361 ADAM SPEAR

ADAM.SPEAR@NOAA.GOV

206-526-4790

Bill To Address

NOAA/NATIONAL MARINE FISHERIES SERV;7600 SAND POINT WAY NORTH EAST;BUILDING 4, ROOM 2089;

SEATTLE, WA, 98115, US

Ship To Address

NOAA/NATIONAL MARINE FISHERIES SERV;7600 SAND POINT WAY NORTH EAST;BUILDING 4, ROOM 2089;

SEATTLE, WA, 98115, US

PRODUCT INFORMATION

Item: 49.LEGACY

Item Description: (LEGACY) SBE 49 FastCAT CTD

Serial: 4929574-0041

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Services Performed:

Performed initial diagnostic evaluation. Performed "POST" cruise calibration. Performed pressure calibration.

| Item | Item Description | Qty |
|------------|---|-----|
| CONCERT49A | Confirm and recertify SBE 49. Complete external inspection; test all | 1 |
| | functions. Cost of major repairs, modifications or calibration is not included. | |
| CAL_49 | SBE 49 FastCAT CTD sensor calibration; conductivity (C&P + recal if necessary), temperature, and pressure | 1 |
| | | |

Unbilled Items

| Item | Item Description | Qty |
|------|------------------|-----|
| | | |



SERVICE REPORT

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

Service Request

Date
Sales Order

Phone

Fax

+1-425-643-9954 www.seabird.com **1005507587** 17-MAY-2019

315570150

+1-425-643-9866

PRODUCT INFORMATION

Item: 49.LEGACY

Item Description: (LEGACY) SBE 49 FastCAT CTD

Serial: 4929574-0042

Special Notes
Services Requested:

Evaluate/Repair Instrumentation.

Perform Routine Calibration Service.

Services Performed:

Performed initial diagnostic evaluation. Performed "POST" cruise calibration. Performed pressure calibration.

| Item Description | Qty |
|---|---|
| Confirm and recertify SBE 49. Complete external inspection; test all | 1 |
| functions. Cost of major repairs, modifications or calibration is not included. | |
| SBE 49 FastCAT CTD sensor calibration; conductivity (C&P + recal if | 1 |
| necessary), temperature, and pressure | |
| | |
| | Confirm and recertify SBE 49. Complete external inspection; test all functions. Cost of major repairs, modifications or calibration is not included. SBE 49 FastCAT CTD sensor calibration; conductivity (C&P + recal if |

Unbilled Items

| Item | Item Description | Qty |
|------|------------------|-----|
| | | |