Comments:

Temperature Calibration Report

Customer:	Pacific Marine E	nvironmental Lab			
Job Number:	65422	D	ate of Repo	rt:	8/19/2011
Model Number	SBE 37SM	S	erial Numbe	er:	37SM29475-2357
Temperature sensors are normally calibrated 'as received', without adjustments, allowing a determination sensor drift. If the calibration identifies a problem, then a second calibration is performed after work is completed. The 'as received' calibration is not performed if the sensor is damaged or non-functional, or by customer request. An 'as received' calibration certificate is provided, listing coefficients to convert sensor frequency to temperature. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients using the program SEACON. The coefficient 'offset' allows a small correction for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair apply only to subsequent data. 'AS RECEIVED CALIBRATION' Performed Not Performed					
Date: 8/19/201	1	Drift since	last cal:	+0.00096	Degrees Celsius/year
Comments:	_		_		
'CALIBRATION	AFTER REPAIR'		☐ Perí	Formed	✓ Not Performed
Date:		Drift since	Last cal:		Degrees Celsius/year